

## Navigation Database Addendum

### **AIRAC 2110 – Issue 15**

**NOTAM A5289/21 effective 14th September 2021**

### **EDDV Hannover**

---

#### **RWY 27L Localizer “IHSW”**

- Frequency 109.50 MHz has been published by mistake, frequency **should read 109.95 MHz**.

Navdata will be updated effective AIRAC cycle 2111.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Monday, 11<sup>th</sup> October 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)