

Navigation Database Addendum

AIRAC 2305 – Issue 11

AIP AD 2.24.8-1 effective 12th December 2013

OJAQ Aqaba / King Hussein Intl

ILS RWY 01, ILS T RWY 01

ILS RWY 01, BAKIR transition

- ACFT has to maintain at or above 5000ft until AQB R194/D5 outbound and at or above 4000ft until AQB R194/D8 outbound. After passing D8 AQB ACFT may descend to at or above 3200ft in procedure turn.

ILS T RWY 01

- Disregard APCH ILS T RWY 01.

Navdata will be updated effective AIRAC cycle 2306.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 12th May 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com