

Navigation Database Addendum

AIRAC 2309 – Issue 2

SUP LI S8/23 effective 9th February 2023

LIMC Milan Malpensa

Runway 17L/35R

Starting from 23 March 2023 temporary upgrading works of runway 17L/35R will take place.

Works are divided in phases that will be announced by NOTAM.

In reduced runway configuration, the coordinates of mobile localizer RWY 35R MLP frequency 109.90 shall read:
N45-39.1 E008-43.7 (N45-39-05.47 E008-43-39.41)

Phase 1:

- RWY 35R/17L closed

Phase 2:

- ILS RWY 35R not available

	Length	TORA	TODA	ASDA	LDA
RWY 35R	3170m	3170m	3230m	3170m	3170m
RWY 17L	3580m				

- First section of RWY 17L used as TWY AA with following temporary intersection take-off:
AA: TORA 3580m TODA 3700m ASDA 3580m
- Procedures ILS Z RWY 35R, ILS Y RWY 35R and LOC Z RWY 35R are suspended

Phase 3:

- ILS RWY 35R downgraded to category one operations.

	Length	TORA	TODA	ASDA	LDA
RWY 35R	3170m	3170m	3230m	3170m	3170m
RWY 17L	3580m				

- First section of RWY 17L used as TWY AA with following temporary intersection take-off:
AA: TORA 3580m TODA 3700m ASDA 3580m

Phase 4:

- RWY 35R/17L closed

Phase 5:

- ILS RWY 35R not available
- Procedures ILS Z RWY 35R, ILS Y RWY 35R and LOC Z RWY 35R are suspended

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 29th August 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com