

Navigation Database Addendum

AIRAC 2309 – Issue 5

AIRAC AMDT SK 65/23 effective 18th May 2023

SKBO Bogota Eldorado Intl

APCHs RNP W RWY 32L (AR), RNP W RWY 32R (AR)

Due to late cancellation of NOTAM A0850/23, following data is not updated in DB:

RNP W RWY 32L (AR)

- speed at BO402, BO403, BO700 should read max.160KT
- ALT at AMVES in MISAP should read (AT) 13000FT

RNP W RWY 32R (AR)

- speed at BO402, BO751 should read max.160KT
- ALT at AMVES in MISAP should read (AT) 13000FT

Navdata will be updated effective AIRAC cycle 2310.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, September 1st, 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com