

Procedures removed from ARINC output Cycle 1807

Type	Procedure	Transition	Reason
3S8_			Grants Pass, OR
	APCH		
	R13	CAMAS	published angle not coincident with calculated one.
	R13		published angle not coincident with calculated one.
AGGH			Henderson / Honiara International
	APCH		
	P06	GGHGF	
	P06	GGHGY	
	P06	GGHWA	
	P06	KOPAU	
	P06		Unconfirmed Waypoint Coordinates
	P24	GGHEB	
	P24	GGHEC	
	P24	GGHED	
	P24	GGHGA	
	P24	GGHGK	
	P24	GGHGL	
	P24		Unconfirmed Waypoint Coordinates

Type	Procedure	Transition	Reason
CPZ3			Trenton / Mountain View, ON
	APCH		
	R06R	LEPAP	source inconsistency, not published in CAP/RCAP
	R06R	SEGEP	source inconsistency, not published in CAP/RCAP
	R06R	ZASER	source inconsistency, not published in CAP/RCAP
	R06R		source inconsistency, not published in CAP/RCAP
	R24L	ALIRA	source inconsistency, not published in CAP/RCAP
	R24L	GADEN	source inconsistency, not published in CAP/RCAP
	R24L	ODBAK	source inconsistency, not published in CAP/RCAP
	R24L		source inconsistency, not published in CAP/RCAP
CYRO			Ottawa / Rockcliffe, ON
	APCH		
	R09	KAXIB	Publizierter Angle passt nicht.
	R09		Publizierter Angle passt nicht.
DGLE			Tamale
	APCH		
	V05-Y	TLE	NOTAM B033/16 - THR 05 displaced
	V05-Y		NOTAM B033/16 - THR 05 displaced
	V05-Z	R140J	NOTAM B033/16 - THR 05 displaced
	V05-Z	R320J	NOTAM B033/16 - THR 05 displaced
	V05-Z	TLE	NOTAM B033/16 - THR 05 displaced
	V05-Z		NOTAM B033/16 - THR 05 displaced

Type	Procedure	Transition	Reason
EDDB			Berlin / Schoenefeld
	SID		
	BELI1A	RW25L	ED A5933/17
	BELI1C	RW07R	ED A5933/17
	BKD1A	RW25L	ED A5933/17
	BKD1C	RW07R	ED A5933/17
	GERG1A	RW25L	ED A5933/17
	GERG1C	RW07R	ED A5933/17
	KLF1A	RW25L	ED A5933/17
	KLF1C	RW07R	ED A5933/17
	TUVA1A	RW25L	ED A5933/17
	TUVA1C	RW07R	ED A5933/17

Type	Procedure	Transition	Reason
APCH			
I07R		KLF	ED A5933/17
I07R		LANUM	ED A5933/17
I07R			ED A5933/17
I25L		ATGUP	ED A5933/17
I25L		FWE	ED A5933/17
I25L		KLF	ED A5933/17
I25L		TERDA	ED A5933/17
I25L			ED A5933/17
L07R		KLF	ED A5933/17
L07R		LANUM	ED A5933/17
L07R			ED A5933/17
L25L		ATGUP	ED A5933/17
L25L		FWE	ED A5933/17
L25L		KLF	ED A5933/17
L25L		TERDA	ED A5933/17
L25L			ED A5933/17
R07R		KLF	ED A5933/17
R07R		LANUM	ED A5933/17
R07R			ED A5933/17

Type	Procedure	Transition	Reason
	R25L	ATGUP	ED A5933/17
	R25L	KLF	ED A5933/17
	R25L	TERDA	ED A5933/17
	R25L		ED A5933/17

EGVN

Brize Norton AB

SID			
	ALPHA	RW07	Different Endfixes not possible
	ALPHA	RW25	Different Endfixes not possible
	BRAVO	RW07	Different Endfixes not possible
	BRAVO	RW25	Different Endfixes not possible

EIME

Baldonnel / Casement

SID			
	DELT11	RW11	source discrepancy: KLY QDR 264/BAL R-233 intersect at D7.75 BAL, not before D7 BAL

FWCL

Blantyre / Chileka Intl

APCH			
	R28	EGL0D	
	R28	XADIS	
	R28		

FZMA

Bukavu / Kavumu

APCH			
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		Incorrect Source: AIRAC AIP SUP S3006/06

Type	Procedure	Transition	Reason
FZNA			Goma Intl
	APCH		
	R17	ASMAT	Unsafe Source
	R17		Unsafe Source
	R35	NESOG	Unsafe Source
	R35	OLIKO	Unsafe Source
	R35	RIXAR	Unsafe Source
	R35		Unsafe Source
HLLT			Tripoli Intl
	SID		
	GARU1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	MIS1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	SARK1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	WLD1C	RW09	VOR/DME TPI new coordinates, procedures not updated

Type	Procedure	Transition	Reason
STAR	GRT1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1E	RW27	VOR/DME TPI new coordinates, procedures not updated

HSSJ

Juba

APCH			
	R13	ALSAP	runway extended, procedure not updated
	R13	ALSOG	runway extended, procedure not updated
	R13	RALSA	runway extended, procedure not updated
	R13		runway extended, procedure not updated

KCLR

Calipatria / Cliff Hatfield Mem, CA

APCH			
	R08	BOREN	
	R08		

Type	Procedure	Transition	Reason
KLCK			Columbus / Rickenbacker Intl, OH
	APCH		
	R05L	GAILL	
	R05L	HIGID	
	R05L	TARTO	
	R05L		not trusted due to calc. angle of 3.16°
KTYR			Tyler Pounds Rgnl, TX
	APCH		
	R22	GODHO	Acc. to NOTAMs 02/006, 02/007 and clari-11551.
	R22	UIM	Acc. to NOTAMs 02/006, 02/007 and clari-11551.
	R22		Acc. to NOTAMs 02/006, 02/007 and clari-11551.
KTYS			Knoxville / Mc Ghee Tyson, TN
	APCH		
	I23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	I23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	L23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R	NEYLN	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	R23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R	VXV	RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15
	V23R		RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15

Type	Procedure	Transition	Reason	
LFOZ			Orleans / St Denis de l'Hotel	
	APCH			
		N23		New RWY 23 coordinates.
		R23	ADATI	New RWY 23 coordinates.
		R23	RISNO	New RWY 23 coordinates.
		R23	UMOGI	New RWY 23 coordinates.
	R23		New RWY 23 coordinates.	

Type	Procedure	Transition	Reason	
LRSV			Suceava / Stefan cel Mare - Suceava	
	APCH			
		R16	BUKOV	FAS DB not provided
		R16	HUMOR	FAS DB not provided
		R16	PASKA	FAS DB not provided
		R16	TOMUC	FAS DB not provided
		R16		FAS DB not provided
		R34	BUKOV	FAS DB not provided
		R34	HUMOR	FAS DB not provided
		R34	PASKA	FAS DB not provided
		R34	RIVKA	FAS DB not provided
		R34	TOMUC	FAS DB not provided
		R34		FAS DB not provided

Type	Procedure	Transition	Reason
SBGW			Guaratingueta, SP
	APCH		
	N02-A	GGT	procedure not compatibel with FMS requirements
	N02-A		procedure not compatibel with FMS requirements
	N20-B	GGT	procedure not compatibel with FMS requirements
	N20-B		procedure not compatibel with FMS requirements
SKQU			Mariquita / Jose Celestino Mutis
	APCH		
	V01-A	MQU	circling apch not leading to RWY, final track offset by more than 15 DEG.
	V01-A		circling apch not leading to RWY, final track offset by more than 15 DEG.
TUPJ			Roadtown / Terrance B. Lettsome Intl.
	APCH		
	N07-B	STT	vertical angle cannot be determined
	N07-B		vertical angle cannot be determined

Type	Procedure	Transition	Reason
USHH			Khanty-Mansiysk
SID			
	ABUT1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	ABUT1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	KUPE1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	KUPE1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	NEMO1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	NEMO1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RATR1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RATR1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RILP1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RILP1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TERD1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TERD1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TUNA1C	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TUNA1D	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)

Type	Procedure	Transition	Reason
STAR	ABUT1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	ABUT1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	KUPE1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	KUPE1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	NEMO1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	NEMO1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	PET1GR	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	PET1HR	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RALE1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RALE1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RATR1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RATR1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RILP1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	RILP1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TAGO1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TAGO1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TERD1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TERD1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	TUNA1G	RW06	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)

Type	Procedure	Transition	Reason
	TUNA1H	RW24	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
APCH			
	R06	HH004	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R06	HH005	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R06	HH006	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R06		NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R24	HH009	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R24	HH010	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R24	HH011	NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)
	R24		NOTAM A2869/18 (dated 23 MAY 18 / WEF 21 JUN 18 until 12 SEP 18)

VGJR

Jessore

APCH			
	V16	JSR	VOR "JSR" re-positioned without revision of apch plates (Ref. AIP SUP 02/17 VG eff. 12OCT17)
	V16		VOR "JSR" re-positioned without revision of apch plates (Ref. AIP SUP 02/17 VG eff. 12OCT17)
	V34	JSR	VOR "JSR" re-positioned without revision of apch plates (Ref. AIP SUP 02/17 VG eff. 12OCT17)
	V34		VOR "JSR" re-positioned without revision of apch plates (Ref. AIP SUP 02/17 VG eff. 12OCT17)

VVTX

Thanh Hoa / Tho Xuan

APCH			
	N31	CB	procedure ALT at NDB "CB" (1690ft) results in an unreasonably high angle of 5.51deg
	N31		procedure ALT at NDB "CB" (1690ft) results in an unreasonably high angle of 5.51deg

	Type	Procedure	Transition	Reason
VYPN				Pathein
		APCH		
		V06	PTN	repositioning of PTN VORDME, AMDT 1/2016
		V06		repositioning of PTN VORDME, AMDT 1/2016
		V24	PTN	repositioning of PTN VORDME, AMDT 1/2016
	V24		repositioning of PTN VORDME, AMDT 1/2016	
WAPP				Ambon / Pattimura
		APCH		
	R22			no RF Center Fix published