

Exclusion List for HWL NavDBs in Cycle 2408

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2408. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex/Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R10-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I04LY	5
	I22RX	5
	I22RY	5
	L04LY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
T22RY	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID		
	BE04C	5
	BE04D	5
	BE04W	5
	BE22A	22
	BE22B	22
	BE22C	5
	BE22D	5
	BE22W	5

EBBL

Kleine Brogel

APCH

	T05R	5
	T23L	5

SID

	BL05A	22
	BL05B	22
	BL05D	22

EBFS

Florennes

SID

	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

EGHC

Penzance/Land s End

APCH

	H07	5
	H16	5
	H25	5
	H34	5

EGHE

St Mary's/Scilly Isles

APCH

	N27	5
	N32	5

EGJA

St Annes/Alderney

APCH

	N08	5
	N26	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGNH			Blackpool
	APCH		
		N10	3
EGNV			Teesside International
	APCH		
		N23	3
EGPO			Stornoway
	APCH		
		L36	3
		N18	3
		N36	3
EGTE			Exeter
	APCH		
		N26	3
EHEH			Eindhoven
	SID		
		EH5	22
ENBL			Forde/Bringeland
	APCH		
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
	APCH		
		J03	1
ENBS			Batsfjord
	APCH		
		J03	1
		J21	1
ENBV			Berlevag
	APCH		
		J06	1
		J24	1
ENHF			Hammerfest
	APCH		
		J04	1
		J22	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J36	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETEB			Ansbach-Katterbach Kaserne
		APCH	
		H08	5
		H26	5
ETIK			Illesheim
		APCH	
		R06	5
		R24	5
ETNG			Geilenkirchen
		SID	
		NG227	22
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
HTKJ			Kilimanjaro Intl
		APCH	
		H09	13
		H27	13
KDLH			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
		T34-X	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
		T36-Z	19
KENV			Wendover
		APCH	
		R08	5
KLSV			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
		T21LZ	19
KMFR			Medford/Rogue Valley Intl-Medf
		APCH	
		R32-Y	5
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5

*See Reason Code table on page R1

Type	Procedure	Reason*
KVPS		Valparaiso/Destin-Ft Walton Be
	APCH	
	T02	19
	T12	19
	T20	19
	T30	19
LFBD		Bordeaux/Merignac
	SID	
	OBLO6Z	5
	ROYA6Z	5
	VAVI6Z	5
LHKE		Kecskemet
	APCH	
	N12	5
	N30	5
LHNY		Nyiregyhaza
	APCH	
	H18-Z	5
	H36-Z	5
LHPA		Papa AB
	APCH	
	N16	5
LJCE		Cerklje ob Krki
	APCH	
	N09	22
MHTG		Tegucigalpa/Toncontin Intl
	APCH	
	H20	13
MMAN		Monterrey/Del Norte Intl
	APCH	
	D20-4	2
MSSS		San Salvador/Ilopango Intl
	APCH	
	V15-W	5
N07		Lincoln Park
	APCH	
	R01	5
	R19	5

*See Reason Code table on page R1

Type	Procedure	Reason*
N40		Pittstown/Sky Manor
	APCH	
	R07	5
	R25	5
	V07	5
N85		Pittstown/Alexandria
	APCH	
	D08	5
NTAA		Tahiti/Faa'a
	SID	
	ARIT4E	5
	ARIT4W	5
NTTE		Tetiaroa
	SID	
	TAVI1E	5
	TAVI1W	5
NZTK		Takaka
	APCH	
	R18-Y	5
NZWB		Woodbourne
	STAR	
	NORTHV	27
	WESTV	27
OPLA		Lahore/Allama Iqbal Intl
	APCH	
	V18LZ	3
	V18RZ	3
	V36L	3
	V36R	3
PACJ		Crooked Creek
	APCH	
	R14	5
	SID	
	AJOFY1	5
PARS		Russian Mission
	APCH	
	R36	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
UHHM			Chegdomyn
		APCH	
		H13	5
		H31	5
UHPK			Ust-Kamchatsk
		STAR	
		DOMUD2	5
UIUU			Ulan-Ude/Mukhino
		APCH	
		I08-Y	5
		N08-Y	5
		N08-Z	5
		STAR	
		BULE5H	5
		OSTU5H	5
		RIDL5H	5
	TOLG5H	5	
UKHK			Kremenchuk/Velyka Kokhnyvka
		APCH	
		N36	5
UNSS			Strezhevoy
		SID	
		BUNA1Z	22
URML			Makhachkala/Uytash
		SID	
		H1A	5
		TA1A	5
		STAR	
		BUIK1E	5
		BUIK1G	5
		GUDE1E	5
	GUDE1G	5	

*See Reason Code table on page R1

	Type	Procedure	Reason*
URRT			Taganrog/Yuzhny
		APCH	
		N10-X	5
		N28-X	5
UUYI			Inta
		SID	
		BABE1A	5
		BABE1B	5
		INTA1A	5
		INTA1B	5
		PERA1A	5
		PERA1B	5
		ROLE1A	5
	ROLE1B	5	
UWKD			Kazan
		APCH	
		V11-X	5
UWSK			Krasny Kut
		SID	
		X003	5
		X070	5
		X107	5
		X130	5
		X156	5
	X351	5	
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
WAJI			Sarmi/Mararena
		APCH	
		H13	5
		H31	5
WAKE			Mappi/Bade
		APCH	
		H02	5
		H20	5

*See Reason Code table on page R1

Type	Procedure	Reason*
WASA		Maybrat/Ayawasi
	APCH	
	H09	5
	H27	5
WASI		Inanwatan
	APCH	
	H08	5
	H26	5
WAUM		Merdey
	APCH	
	H27	5

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55