

Procedures removed from ARINC output Cycle 2602

	Type	Procedure	Transition	Reason
AYKV				Kavieng
		APCH		
		R30	YKVED	Notam AY A1069/22 THR RWY 30 coordinates changed
		R30	YKVEE	Notam AY A1069/22 THR RWY 30 coordinates changed
		R30	YKVEG	Notam AY A1069/22 THR RWY 30 coordinates changed
		R30		Notam AY A1069/22 THR RWY 30 coordinates changed
DAUB				Biskra / Mohamed Khider
		APCH		
		I31	BIS	RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
		I31		RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
DNMN				Minna
		APCH		
		I05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		I05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		L05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		L05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V23	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V23		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.

	Type	Procedure	Transition	Reason
EGVN				Brize Norton AB
	SID			
		ALPHA	RW07	Different Endfixes not possible
		ALPHA	RW25	Different Endfixes not possible
		BRAVO	RW07	Different Endfixes not possible
		BRAVO	RW25	Different Endfixes not possible
FMMS				Sainte Marie
	APCH			
		N01	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N01		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N19	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N19		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
FNLU				Luanda / 4th of February
	APCH			
		I23	ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
		I23	R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
		I23		FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
		L23	ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
		L23	R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
		L23		FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.

	Type	Procedure	Transition	Reason
FZMA				Bukavu / Kavumu
		APCH		
		R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
		R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
		R35		Incorrect Source: AIRAC AIP SUP S3006/06
HKLK				Lokichoggio
		APCH		
		H27	EPSUT	HK Notam B0002/21
		H27		HK Notam B0002/21
HLLT				Tripoli Intl
		STAR		
		IZD1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
		SINA1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
KCLR				Calipatria / Cliff Hatfield Mem, CA
		APCH		
		R08	BOREN	
		R08		
KLCK				Columbus / Rickenbacker Intl, OH
		APCH		
		R05L	GAILL	
		R05L	HIGID	
		R05L	TARTO	
		R05L		not trusted due to calc. angle of 3.16°
OAKB				Kabul Intl
		SID		
		TAPIS2	RW11	RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)

Type	Procedure	Transition	Reason
------	-----------	------------	--------

APCH

R29

RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)

UERP

Poliarny

SID

ABNI1F

RW36

NTM UE C3683/25 (proc not to be used)

BAGO1F

RW36

NTM UE C3683/25 (proc not to be used)

BALU1F

RW36

NTM UE C3683/25 (proc not to be used)

DEDO1F

RW36

NTM UE C3683/25 (proc not to be used)

FADR1F

RW36

NTM UE C3683/25 (proc not to be used)

GILA1F

RW36

NTM UE C3683/25 (proc not to be used)

INDI1F

RW36

NTM UE C3683/25 (proc not to be used)

NERD1F

RW36

NTM UE C3683/25 (proc not to be used)

OGON1F

RW36

NTM UE C3683/25 (proc not to be used)

PELI1F

RW36

NTM UE C3683/25 (proc not to be used)

PIRO1F

RW36

NTM UE C3683/25 (proc not to be used)

RUSE1F

RW36

NTM UE C3683/25 (proc not to be used)

SUGI1F

RW36

NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
STAR			
	ABNI1L	RW18	NTM UE C3683/25 (proc not to be used)
	ABNI1L	RW36	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW18	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW36	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW18	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW36	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW18	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW36	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW18	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW36	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW18	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW36	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW18	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW36	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW18	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW36	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW18	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW36	NTM UE C3683/25 (proc not to be used)
	PELI1L	RW18	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
	PELI1L	RW36	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW18	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW36	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW18	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW36	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW18	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW36	NTM UE C3683/25 (proc not to be used)
APCH			
	J18	RP003	NTM UE C3298/24
	J18	RP004	NTM UE C3298/24
	J18		NTM UE C3298/24
	V18	PLR	NTM UE C3683/25 (proc not to be used)
	V18		NTM UE C3683/25 (proc not to be used)
	V36	PLR	NTM UE C3683/25 (proc not to be used)
	V36		NTM UE C3683/25 (proc not to be used)

UTAK

Turkmenbashi

APCH

N34R	NTM UT O0023/24 (no minma for new situation based on this NTM) pending new charts
------	---

Type	Procedure	Transition	Reason
UUOO Voronezh / Chertovitskoye			
APCH			
	J30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	J30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
VLVT Vientiane / Wattay Intl			
SID			
	BIK1C	RW31	Lao AIRAC SUP A04/25 - WEF 30 OCT 2025. Mismatch between graphical depiction and procedure text
YPTN Tindal, NT			
APCH			
	I14-Z	TN	SUP H 27/22
	I14-Z		SUP H 27/22