

Procedures removed from ARINC output Cycle 2603

Type	Procedure	Transition	Reason
AYKV			Kavieng
	APCH		
	R30	YKVED	Notam AY A1069/22 THR RWY 30 coordinates changed
	R30	YKVEE	Notam AY A1069/22 THR RWY 30 coordinates changed
	R30	YKVEG	Notam AY A1069/22 THR RWY 30 coordinates changed
	R30		Notam AY A1069/22 THR RWY 30 coordinates changed
DAUB			Biskra / Mohamed Khider
	APCH		
	I31	BIS	RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
	I31		RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
DNMN			Minna
	APCH		
	I05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	I05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	L05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	L05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	V05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	V05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	V23	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
	V23		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.

Type	Procedure	Transition	Reason
EGVN			Brize Norton AB
	SID		
	ALPHA	RW07	Different Endfixes not possible
	ALPHA	RW25	Different Endfixes not possible
	BRAVO	RW07	Different Endfixes not possible
	BRAVO	RW25	Different Endfixes not possible

Type	Procedure	Transition	Reason
FMMS			Sainte Marie
	APCH		
	N01	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
	N01		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
	N19	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
	N19		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD

Type	Procedure	Transition	Reason
FNLU			Luanda / 4th of February
	APCH		
	I23	ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	I23	R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	I23		FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23	ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23	R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23		FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.

Type	Procedure	Transition	Reason
FZMA			Bukavu / Kavumu
	APCH		
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		Incorrect Source: AIRAC AIP SUP S3006/06
HKLK			Lokichoggio
	APCH		
	H27	EPSUT	HK Notam B0002/21
	H27		HK Notam B0002/21
HLLT			Tripoli Intl
	STAR		
	IZD1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
	SINA1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
KLCK			Columbus / Rickenbacker Intl, OH
	APCH		
	R05L	GAILL	
	R05L	HIGID	
	R05L	TARTO	
	R05L		not trusted due to calc. angle of 3.16°

Type	Procedure	Transition	Reason
LTAD			Ankara / Etimesgut
APCH			
	H11L	AYHAN	AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	H11L		AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	I11LY	ENDER	AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	I11LY		AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	I11LZ	FETIH	AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	I11LZ		AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	L11LY	ENDER	AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	L11LY		AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	L11LZ	FETIH	AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
	L11LZ		AIRAC AMDT 03/2026 - THR coordinates changed, procedures not updated
OAKB			Kabul Intl
SID			
	TAPIS2	RW11	RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)
APCH			
	R29		RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)

Type	Procedure	Transition	Reason
UERP			Poliarny
	SID		
	ABNI1F	RW36	NTM UE C3683/25 (proc not to be used)
	BAGO1F	RW36	NTM UE C3683/25 (proc not to be used)
	BALU1F	RW36	NTM UE C3683/25 (proc not to be used)
	DEDO1F	RW36	NTM UE C3683/25 (proc not to be used)
	FADR1F	RW36	NTM UE C3683/25 (proc not to be used)
	GILA1F	RW36	NTM UE C3683/25 (proc not to be used)
	INDI1F	RW36	NTM UE C3683/25 (proc not to be used)
	NERD1F	RW36	NTM UE C3683/25 (proc not to be used)
	OGON1F	RW36	NTM UE C3683/25 (proc not to be used)
	PELI1F	RW36	NTM UE C3683/25 (proc not to be used)
	PIRO1F	RW36	NTM UE C3683/25 (proc not to be used)
	RUSE1F	RW36	NTM UE C3683/25 (proc not to be used)
	SUGI1F	RW36	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
STAR	ABNI1L	RW18	NTM UE C3683/25 (proc not to be used)
	ABNI1L	RW36	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW18	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW36	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW18	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW36	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW18	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW36	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW18	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW36	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW18	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW36	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW18	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW36	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW18	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW36	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW18	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW36	NTM UE C3683/25 (proc not to be used)
	PELI1L	RW18	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
	PELI1L	RW36	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW18	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW36	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW18	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW36	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW18	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW36	NTM UE C3683/25 (proc not to be used)
APCH			
	J18	RP003	NTM UE C3298/24
	J18	RP004	NTM UE C3298/24
	J18		NTM UE C3298/24
	V18	PLR	NTM UE C3683/25 (proc not to be used)
	V18		NTM UE C3683/25 (proc not to be used)
	V36	PLR	NTM UE C3683/25 (proc not to be used)
	V36		NTM UE C3683/25 (proc not to be used)

UTAK

Turkmenbashi

APCH			
	N34R		NTM UT O0023/24 (no minma for new situation based on this NTM) pending new charts

Type	Procedure	Transition	Reason
UUOO			Voronezh / Chertovitskoye
	APCH		
	J30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	J30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.

Type	Procedure	Transition	Reason
UUYH			Ukhta
	APCH		
	I35-X	BF	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-X	BFRT	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-X		NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-Y	UHT	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-Y		NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-Z	YH016	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-Z	YH018	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	I35-Z		NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-X	BF	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-X	BFRT	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-X		NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-Y	UHT	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-Y		NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-Z	YH016	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-Z	YH018	NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
	L35-Z		NTM UL C0794/26 (PERM), ILS (LOC and GP) withdrawn from service. ILS/LOC charts for RWY 35 unusable.
VLVT			Vientiane / Wattay Intl
	SID		
	BIK1C	RW31	Lao AIRAC SUP A04/25 - WEF 30 OCT 2025. Mismatch between graphical depiction and procedure text

Type	Procedure	Transition	Reason
YPTN			Tindal, NT
	APCH		
	I14-Z	TN	SUP H 27/22
	I14-Z		SUP H 27/22