

Exclusion List for HWL NavDBs in Cycle 2604

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2604. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
01D2		May/Flying Joseph Ranch
	APCH	
	R11-M	40
	SID	
	YOYYU1	40
	ZAROD1	40
10X		Uvalde/Ox Ranch
	APCH	
	R17-M	40
	R35-M	40
17XS		Dublin/Quahadi Ranch
	APCH	
	R01	40
	R19	40
640G		Mitchell/Antone Ranch
	APCH	
	R25-M	40
	SID	
	RIFTE1	40
7FL6		Daytona Beach/Spruce Creek
	APCH	
	R06	40
CAJ9		Fort Ware
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
CAM2		Misaw Lake
	APCH	
	R01	40
	R19	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CBH2			Helmet
		APCH	
		R12	40
		R30	40
CBN9			Tsay Keh
		APCH	
		R31	40
CBQ7			Kemess Creek
		APCH	
		R11-Y	40
		R11-Z	40
		R29	40
	SID		
		AVRED1	40
CBW4			Bob Quinn Lake
		APCH	
		R15-Y	40
		R15-Z	40
CBX7			Tumbler Ridge
		APCH	
		R20	40
	SID		
		KISKK6	40
CCB2			Seabee Mine
		APCH	
		R05	40
		R23	40
CCE3			Juniper
		APCH	
		R02	40
		R20	40
CCJ3			Boston Brook
		APCH	
		R02	40
		R20	40
CCL3			Christina Lake
		APCH	
		R08	40
		R26	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CCL6			Chilko Lake/Wilderness Lodge
	APCH		
		R16	40
CCR3			Florenceville
	APCH		
		R18-Y	40
		R18-Z	40
		R36-Y	40
		R36-Z	40
CCS4			Chipman
	APCH		
		R09	40
		R27	40
CDA5			St Andrews/Codroy Valley
	SID		
		ODP18	40
		ODP36	40
CDJ4			Clearwater
	APCH		
		R14	40
		R32	40
CDJ5			Strathmore/D.J. Murray
	APCH		
		R16	40
		R34	40
CDP3			Utik Lake/Dennis G Panches Fie
	APCH		
		R09	40
		R27	40
CDT5			Bouctouche
	APCH		
		R09	40
		R27	40
CDU6			Doaktown
	APCH		
		R11	40
		R29	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CDV2			Downs Gulch
		APCH	
		R05	40
		R23	40
CEC4			Hinton/Jasper-Hinton
		APCH	
		R02	40
CEE5			Wabasca
		APCH	
		R07	40
		R25	40
CEG8			North Seal River
		APCH	
		R03	40
		R21	40
CEH3			Ponoka
		APCH	
		R16-Y	40
		R34-Y	40
CEP3			Barrhead
		APCH	
		R07	40
		R25	40
CEU9			Sambaa K'e
		APCH	
		R04-Y	40
		R22-Y	40
CFH4			Fox Harbour
		APCH	
		R15	40
		R33	40
CFN6			Primrose
		APCH	
		R14	40
	SID		
		VETPA1	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CFQ6			Pelly Crossing
		APCH	
		R08	40
		R26	40
CFT8			Pelican
		APCH	
		R07	40
		R25	40
CHB3			Hope Bay
		APCH	
		R01-Y	40
		R01-Z	40
		R19	40
CJA3			Morden Rgnl
		APCH	
		R10	40
		R28	40
CJB3			Steinbach
		APCH	
		R15	40
CJK3			Beauval
		APCH	
		R10	40
		R28	40
CJL4			La Loche
		APCH	
		R12	40
		R30	40
CJL8			Kasba Lake
		APCH	
		R02	40
		R20	40
CJP9			Charlot River
		APCH	
		R05-Y	40
		R23	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CJQ3			Carlyle
		APCH	
		R11	40
		R29	40
CJQ4			Maple Creek
		APCH	
		R06	40
CJW4			Pelican Narrows
		APCH	
		R01	40
		R19	40
CJY4			Sandy Bay
		APCH	
		R05	40
		R23	40
CKB2			Patuanak
		APCH	
		R14	40
		R32	40
CKD5			Kipling
		APCH	
		R10	40
CKM8			Opapimiskan Lake
		APCH	
		R12	40
		R30	40
CKZ3			Elk Island
		APCH	
		R06	40
		R24	40
CKZ7			Winkler
		APCH	
		R09	40
		R27	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CMB2		Meadowbank
	APCH	
	R12-Y	40
	R12-Z	40
	R30-Y	40
	R30-Z	40
CMB7		Maxville/Bourdon Farm
	APCH	
	R16	40
CNL9		Nueltin Lake
	APCH	
	R02	40
	R20	40
CNV8		Edenvale
	APCH	
	R13	40
CRL4		Kirby Lake
	APCH	
	R08	40
	R26	40
	SID	
	KIRBY5	40
CRW4		Arctic Watch Lodge
	APCH	
	R01	40
	R19	40
	SID	
	ANEGU1	40
CSR3		Victoriaville Andre-Fortin
	APCH	
	R24	40
CSR8		La Sarre
	APCH	
	R36	40
CSZ4		St-Frederic
	APCH	
	R23	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CTH7		Riviere-Aux-Saumons
	APCH	
	R10	40
	R28	40
CVB2		Voisey's Bay
	APCH	
	R10	40
	R28	40
CYAU		Liverpool/South Shore Rgnl
	APCH	
	R07	40
	R25	40
	SID	
	ODP07	40
	ODP25	40
CYBG		Bagotville
	APCH	
	I11-X	40
	I29-X	40
	L11-X	40
	L29-X	40
	R11-X	40
	R29-X	40
CYCZ		Fairmont Hot Springs
	SID	
	TEVED1	40
CYDL		Dease Lake
	APCH	
	R03-X	40
	R03-Y	40
	R03-Z	40
	R21-X	40
	R21-Y	40
	R21-Z	40
	SID	
	OMRUN2	40
	TIBID1	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
CYDM			Ross River
	APCH	R09	40
CYFR			Fort Resolution
	APCH	R13-Y	40
		R31-Y	40
CYIB			Atikokan Muni
	APCH	R04	40
		R22	40
CYKA			Kamloops
	APCH	I09	40
		L27-Y	40
		R09-Y	40
		R09-Z	40
		R27-Y	40
		R27-Z	40
CYLS			Barrie-Orilla/Barrie-Orillia /
	APCH	R10	40
CYLW			Kelowna
	APCH	I16-Y	40
		I16-Z	40
		R16-V	40
		R16-X	40
	R34-Z	40	
CYMW			Maniwaki
	APCH	R21	40
CYNN			Nejanilini Lake
	APCH	R18	40
		R36	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CYPZ		Burns Lake
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
	SID	
	CYPZ6	40
	ODPV	40
CYSH		Smith Falls-Montague/Russ Beac
	APCH	
	R06	40
	R24	40
CYTB		Tillsonburg
	APCH	
	R26	40
CYTZ		Toronto/B Bishop Toronto City
	APCH	
	R08-W	40
	R08-X	40
	R26-X	40
CYZG		Salluit
	APCH	
	R03-X	40
CYZW		Teslin
	APCH	
	R09-Y	40
	R27-X	40
CZAM		Salmon Arm
	APCH	
	R14	40
	R32	40
CZML		South Cariboo/108 Mile
	APCH	
	R15	40
	R33	40

*See Reason Code table on page R1

Type	Procedure	Reason*
CZPO		Pinehouse Lake
	APCH	
	R16	40
	R34	40
DATM		Bordj Mokhtar
	APCH	
	V26	2
EBBE		Beauvechain
	SID	
	BE22A	22
	BE22B	22
EBFS		Florennes
	SID	
	FS08A	22
	FS08B	22
	FS08C	22
	FS08D	22
	FS08E	22
	FS26A	22
	FS26B	22
	FS26C	22
	FS26D	22
FS26E	22	
EGNH		Blackpool
	APCH	
	N10	3
EGNV		Teesside International
	APCH	
	N23	3
EGPO		Stornoway
	APCH	
	L36	3
	N18	3
	N36	3
EGTE		Exeter
	APCH	
	N26	3

*See Reason Code table on page R1

	Type	Procedure	Reason*
EHEH			Eindhoven
	SID		
		EH5	22
ENBL			Forde/Bringeland
	APCH		
	J07		1
		J25	1
ENBN			Bronnoysund/Bronnoy
	APCH		
		J03	1
ENBS			Batsfjord
	APCH		
	J03		1
		J21	1
ENBV			Berlevag
	APCH		
	J06		1
		J24	1
ENHF			Hammerfest
	APCH		
	J04-Z		1
		J22-Z	1
ENHK			Hasvik
	APCH		
	J11		1
		J29	1
ENLK			Leknes
	APCH		
		J20	1
ENMH			Mehamn
	APCH		
	J17		1
		J35	1
ENNM			Namsos
	APCH		
	J07		1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J36	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVV			Vadso
		APCH	
		J07	1
		J25	1
ETNG			Geilenkirchen
		SID	
		NG227	22
FA54			Placida/Coral Creek
		APCH	
		R05	40
		R23	40
KASE			Aspen-Pitkin County/Sardy Fld
		APCH	
		L15	40
KDLH			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
	T34-X	19	
KDZB			Horseshoe Bay Resort
		APCH	
		R17	40
	R35	40	
KEGE			Eagle County Rgnl
		APCH	
		I25	40
	L25-Y	40	
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
	T36	19	
KHIF			Ogden/Hill AFB
		SID	
		DEVLN1	40
	LGTNG1	40	
KJPX			East Hampton Town
		APCH	
		R10-M	40
	R28-M	40	
KLSV			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
	T21LZ	19	
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01-Y	19
		T01-Z	19
		T19-Y	19
	T19-Z	19	

*See Reason Code table on page R1

	Type	Procedure	Reason*
KMTN			Baltimore/Martin State
		APCH	
		T15	41
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KNLC			Lemoore NAS / Reeves Fld
		SID	
		LEM2EO	40
		REV5BU	40
KNQX			Key West NAS (Boca Chica Fld)
		SID	
		NQX6	40
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
	T32RZ	19	
KTCM			Tacoma/McChord Fld /Joint Bas
		STAR	
		WHYTE7	40
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T02	19
		T12	19
		T20	19
		T30	19
KWAL			Wallops Island/Wallops Flight
		APCH	
		T10	41

*See Reason Code table on page R1

Type	Procedure	Reason*
KWRB		Warner Robins/Robins AFB
	APCH	
	T15-Y	19
	T15-Z	19
	T33-Y	19
	T33-Z	19
LEZG		Zaragoza
	APCH	
	T12RZ	19
	T30RZ	19
LJCE		Cerklje ob Krki
	APCH	
	N08	22
MMAN		Monterrey/Del Norte Intl
	APCH	
	V20-W	11
NZWB		Woodbourne
	STAR	
	NORTHV	27
	WESTV	27
OPKC		Karachi/Jinnah Intl
	APCH	
	V25LY	3
	V25RY	3
OPLA		Lahore/Allama Iqbal Intl
	APCH	
	V18LZ	3
	V18RZ	3
	V36L	3
	V36R	3
PAAD		Deadhorse/Point Thomson Aistr
	APCH	
	R05	40
	R23	40
PABP		Deadhorse/Badami
	APCH	
	R04	40
	R22	40

*See Reason Code table on page R1

	Type	Procedure	Reason*
PACZ			Cape Romanzof LRRS
	APCH	R02	40
PADG			Red Dog
	APCH	R03	40
		R03-P	40
	SID	SICOV1	40
PADK			Adak Island/Adak
	APCH	R23-N	40
PADQ			Kodiak
	APCH	I26-Z	40
		L26-Z	40
PADU			Unalaska
	APCH	N13	40
		N31	40
		R13	40
		R13-M	40
		R31	40
		R31-M	40
	SID	DUT1	40
PAGB			Galbraith Lake
	APCH	R14	40
	SID	ARTIC2	40
PAIM			Utopia Creek/Indian Mountain L
	APCH	N25	40
		R25	40
	SID	CLYDD4	40

*See Reason Code table on page R1

Type	Procedure	Reason*
PAJN		Juneau Intl
	APCH	
	R08-T	40
PAKU		Kuparuk/Ugnu-Kuparuk
	APCH	
	I06	40
	I24	40
	L06	40
	L24	40
	R06	40
	R24	40
PAKW		Klawock
	APCH	
	R02-Z	40
PALP		Nuiqsut/Alpine Airstrip
	APCH	
	R04	40
	R22	40
	SID	
	NUQST1	40
PALU		Cape Lisburne LRRS
	APCH	
	R27	40
	SID	
	GRAAY4	40
	LUR8	40
PAPG		Petersburg James A Johnson
	APCH	
	R23-P	40
PAPR		Prospect Creek
	APCH	
	R01-M	40
	R01-Z	40
	R19	40
	SID	
	CYCLE1	40

*See Reason Code table on page R1

Type	Procedure	Reason*
PASV		Sparrevohn LRRS
	APCH	
	N35	40
	R35	40
PATC		Tin City LRRS
	APCH	
	Q35	40
	R35	40
	SID	
	HONPO3	40
	JEKLI3	40
	TNC5	40
PATL		Takotna/Tatalina LRRS
	APCH	
	R35	40
	SID	
	TLJ4	40
PAVD		Valdez Pioneer Fld
	SID	
	FJORD1	40
	JOH2	40
RJBB		Kansai Intl
	STAR	
	CDO1	42
	CDO2F	42
	CDO20	42
	CDO3	42
	CDO4	42
RKSM		Seoul Domestic
	APCH	
	I20	22
	I20-Z	22
	L19	22
	L19-Z	22
	L20	22
	L20-Z	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
RKSO			Songtan-Si/Osan AB
		APCH	
		T09LZ	19
		T09RZ	19
		T27LZ	19
		T27RZ	19
TX25			Athens/Lochridge Ranch
		APCH	
		N17	40
UNSS			Strezhevoy
		SID	
		BUNA1Z	22
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
40	Procedure requires special authorization
41	AF leg in final
42	Profile descent STARS

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55