

## Exclusion List for HWL NavDBs in Cycle 2606

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2606. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
<b>01D2</b>		May/Flying Joseph Ranch
	APCH	
	R11-M	40
	SID	
	YOYYU1	40
	ZAROD1	40
<b>10X</b>		Uvalde/Ox Ranch
	APCH	
	R17-M	40
	R35-M	40
<b>17XS</b>		Dublin/Quahadi Ranch
	APCH	
	R01	40
	R19	40
<b>640G</b>		Mitchell/Antone Ranch
	APCH	
	R25-M	40
	SID	
	RIFTE1	40
<b>7FL6</b>		Daytona Beach/Spruce Creek
	APCH	
	R06	40
<b>CAJ9</b>		Fort Ware
	APCH	
	R11-Y	40
	R11-Z	40
	R29-Y	40
	R29-Z	40
<b>CAM2</b>		Misaw Lake
	APCH	
	R01	40
	R19	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CBH2</b>			Helmet
		APCH	
		R12	40
		R30	40
<b>CBN9</b>			Tsay Keh
		APCH	
		R31	40
<b>CBQ7</b>			Kemess Creek
		APCH	
		R11-Y	40
		R11-Z	40
		R29	40
	SID		
		AVRED1	40
<b>CBW4</b>			Bob Quinn Lake
		APCH	
		R15-Y	40
		R15-Z	40
<b>CBX7</b>			Tumbler Ridge
		APCH	
		R20	40
	SID		
		KISKK6	40
<b>CCB2</b>			Seabee Mine
		APCH	
		R05	40
		R23	40
<b>CCE3</b>			Juniper
		APCH	
		R02	40
		R20	40
<b>CCJ3</b>			Boston Brook
		APCH	
		R02	40
		R20	40
<b>CCL3</b>			Christina Lake
		APCH	
		R08	40
		R26	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CCL6</b>			Chilko Lake/Wilderness Lodge
	APCH		
		R16	40
<b>CCR3</b>			Florenceville
	APCH		
		R18-Y	40
		R18-Z	40
		R36-Y	40
		R36-Z	40
<b>CCS4</b>			Chipman
	APCH		
		R09	40
		R27	40
<b>CDA5</b>			St Andrews/Codroy Valley
	SID		
		ODP18	40
		ODP36	40
<b>CDJ4</b>			Clearwater
	APCH		
		R14	40
		R32	40
<b>CDJ5</b>			Strathmore/D.J. Murray
	APCH		
		R16	40
		R34	40
<b>CDP3</b>			Utik Lake/Dennis G Panches Fie
	APCH		
		R09	40
		R27	40
<b>CDT5</b>			Bouctouche
	APCH		
		R09	40
		R27	40
<b>CDU6</b>			Doaktown
	APCH		
		R11	40
		R29	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CDV2</b>			Downs Gulch
		APCH	
		R05	40
		R23	40
<b>CEC4</b>			Hinton/Jasper-Hinton
		APCH	
		R02	40
<b>CEE5</b>			Wabasca
		APCH	
		R07	40
		R25	40
<b>CEG8</b>			North Seal River
		APCH	
		R03	40
		R21	40
<b>CEH3</b>			Ponoka
		APCH	
		R16-Y	40
		R34-Y	40
<b>CEP3</b>			Barrhead
		APCH	
		R07	40
		R25	40
<b>CEU9</b>			Sambaa K'e
		APCH	
		R04-Y	40
		R22-Y	40
<b>CFH4</b>			Fox Harbour
		APCH	
		R15	40
		R33	40
<b>CFN6</b>			Primrose
		APCH	
		R14	40
	SID		
		VETPA1	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CFQ6</b>			Pelly Crossing
		APCH	
		R08	40
		R26	40
<b>CFT8</b>			Pelican
		APCH	
		R07	40
		R25	40
<b>CHB3</b>			Hope Bay
		APCH	
		R01-Y	40
		R01-Z	40
		R19	40
<b>CJA3</b>			Morden Rgnl
		APCH	
		R10	40
		R28	40
<b>CJB3</b>			Steinbach
		APCH	
		R15	40
<b>CJK3</b>			Beauval
		APCH	
		R10	40
		R28	40
<b>CJL4</b>			La Loche
		APCH	
		R12	40
		R30	40
<b>CJL8</b>			Kasba Lake
		APCH	
		R02	40
		R20	40
<b>CJP9</b>			Charlot River
		APCH	
		R05-Y	40
		R23	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CJQ3</b>			Carlyle
		APCH	
		R11	40
		R29	40
<b>CJQ4</b>			Maple Creek
		APCH	
		R06	40
<b>CJW4</b>			Pelican Narrows
		APCH	
		R01	40
		R19	40
<b>CJY4</b>			Sandy Bay
		APCH	
		R05	40
		R23	40
<b>CKB2</b>			Patuanak
		APCH	
		R14	40
		R32	40
<b>CKD5</b>			Kipling
		APCH	
		R10	40
<b>CKM8</b>			Opapimiskan Lake
		APCH	
		R12	40
		R30	40
<b>CKZ3</b>			Elk Island
		APCH	
		R06	40
		R24	40
<b>CKZ7</b>			Winkler
		APCH	
		R09	40
		R27	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CMB2</b>			Meadowbank
		APCH	
		R12-Y	40
		R12-Z	40
		R30-Y	40
		R30-Z	40
<b>CMB7</b>			Maxville/Bourdon Farm
		APCH	
		R16	40
<b>CNL9</b>			Nueltin Lake
		APCH	
		R02	40
		R20	40
<b>CNV8</b>			Edenvale
		APCH	
		R13	40
<b>CRL4</b>			Kirby Lake
		APCH	
		R08	40
		R26	40
		SID	
		KIRBY5	40
<b>CRW4</b>			Arctic Watch Lodge
		APCH	
		R01	40
		R19	40
	SID		
		ANEGU1	40
<b>CSR3</b>			Victoriaville Andre-Fortin
		APCH	
		R24	40
<b>CSR8</b>			La Sarre
		APCH	
		R36	40
<b>CSZ4</b>			St-Frederic
		APCH	
		R23	40

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>CTH7</b>		Riviere-Aux-Saumons
	APCH	
	R10	40
	R28	40
<b>CVB2</b>		Voisey's Bay
	APCH	
	R10	40
	R28	40
<b>CYAU</b>		Liverpool/South Shore Rgnl
	APCH	
	R07	40
	R25	40
	SID	
	ODP07	40
	ODP25	40
<b>CYBG</b>		Bagotville
	APCH	
	I11-X	40
	I29-X	40
	L11-X	40
	L29-X	40
	R11-X	40
	R29-X	40
<b>CYCZ</b>		Fairmont Hot Springs
	SID	
	TEVED1	40
<b>CYDL</b>		Dease Lake
	APCH	
	R03-X	40
	R03-Y	40
	R03-Z	40
	R21-X	40
	R21-Y	40
	R21-Z	40
	SID	
	OMRUN2	40
	TIBID1	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>CYDM</b>			Ross River
		APCH	
		R09	40
<b>CYFR</b>			Fort Resolution
		APCH	
		R13-Y	40
		R31-Y	40
<b>CYIB</b>			Atikokan Muni
		APCH	
		R04	40
		R22	40
<b>CYKA</b>			Kamloops
		APCH	
		I09	40
		L27-Y	40
		R09-Y	40
		R09-Z	40
		R27-Y	40
	R27-Z	40	
<b>CYLW</b>			Kelowna
		APCH	
		I16-Y	40
		I16-Z	40
		R16-V	40
		R16-X	40
	R34-Z	40	
<b>CYMW</b>			Maniwaki
		APCH	
		R21	40
<b>CYNN</b>			Nejanilini Lake
		APCH	
		R18	40
		R36	40
<b>CYPZ</b>			Burns Lake
		APCH	
		R11-Y	40
		R11-Z	40
		R29-Y	40
		R29-Z	40

\*See Reason Code table on page R1

Type	Procedure	Reason*
SID		
	CYPZ6	40
	ODPV	40
<b>CYSH</b>		Smith Falls-Montague/Russ Beac
	APCH	
	R06	40
	R24	40
<b>CYTB</b>		Tillsonburg
	APCH	
	R26	40
<b>CYTZ</b>		Toronto/B Bishop Toronto City
	APCH	
	R08-W	40
	R08-X	40
	R26-X	40
<b>CYZG</b>		Salluit
	APCH	
	R03-X	40
<b>CYZW</b>		Teslin
	APCH	
	R09-Y	40
	R27-X	40
<b>CZAM</b>		Salmon Arm
	APCH	
	R14	40
	R32	40
<b>CZML</b>		South Cariboo/108 Mile
	APCH	
	R15	40
	R33	40
<b>CZPO</b>		Pinehouse Lake
	APCH	
	R16	40
	R34	40
<b>DATM</b>		Bordj Mokhtar
	APCH	
	V26	2

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>EBBE</b>		Beauvechain
	SID	
	BE22A	22
	BE22B	22
<b>EBFS</b>		Florennes
	SID	
	FS08A	22
	FS08B	22
	FS08C	22
	FS08D	22
	FS08E	22
	FS26A	22
	FS26B	22
	FS26C	22
	FS26D	22
	FS26E	22
<b>EGNH</b>		Blackpool
	APCH	
	N10	3
<b>EGNV</b>		Teesside International
	APCH	
	N23	3
<b>EGPO</b>		Stornoway
	APCH	
	L36	3
	N18	3
	N36	3
<b>EGTE</b>		Exeter
	APCH	
	N26	3
<b>EHEH</b>		Eindhoven
	SID	
	EH5	22
<b>ENBL</b>		Forde/Bringeland
	APCH	
	J07	1
	J25	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENBN</b>			Bronnoysund/Bronnoy
	APCH		
		J03	1
<b>ENBS</b>			Batsfjord
	APCH		
		J03	1
		J21	1
<b>ENBV</b>			Berlevag
	APCH		
		J06	1
		J24	1
<b>ENHF</b>			Hammerfest
	APCH		
		J04-Z	1
		J22-Z	1
<b>ENHK</b>			Hasvik
	APCH		
		J11	1
		J29	1
<b>ENLK</b>			Leknes
	APCH		
		J20	1
<b>ENMH</b>			Mehamn
	APCH		
		J17	1
		J35	1
<b>ENNM</b>			Namsos
	APCH		
		J07	1
		J25	1
<b>ENRM</b>			Rorvik/Ryum
	APCH		
		J04	1
		J22	1
<b>ENRS</b>			Rost
	APCH		
		J02	1
		J20	1

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>ENSH</b>			Svolvaer/Helle
		APCH	
		J36	1
<b>ENSS</b>			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
<b>ENST</b>			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
<b>ENVD</b>			Vadso
		APCH	
		J07	1
		J25	1
<b>ETNG</b>			Geilenkirchen
		SID	
		NG227	22
<b>FA54</b>			Placida/Coral Creek
		APCH	
		R05	40
		R23	40
<b>KASE</b>			Aspen-Pitkin County/Sardy Fld
		APCH	
		L15	40
<b>KDLH</b>			Duluth Intl
		APCH	
		T09	19
		T09-Y	19
		T09-Z	19
<b>KDYS</b>			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T16-X	19
		T34-W	19
		T34-X	19

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>KDZB</b>			Horseshoe Bay Resort
		APCH	
		R17	40
		R35	40
<b>KEGE</b>			Eagle County Rgnl
		APCH	
		I25	40
		L25-Y	40
<b>KEGI</b>			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18-Y	19
		T18-Z	19
		T36	19
<b>KHIF</b>			Ogden/Hill AFB
		SID	
		DEVLN1	40
		LGTNG1	40
<b>KJPX</b>			East Hampton Town
		APCH	
		R10-M	40
		R28-M	40
<b>KLSV</b>			Las Vegas/Nellis AFB
		APCH	
		T03R	19
		T21LX	19
		T21LY	19
		T21LZ	19
<b>KMTC</b>			Mount Clemens/Selfridge ANGB
		APCH	
		T01-Y	19
		T01-Z	19
		T19-Y	19
		T19-Z	19
<b>KMTN</b>			Baltimore/Martin State
		APCH	
		T15	41
		V15	11

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>KNDZ</b>			Milton/Whiting Fld NAS South
		APCH	
		T32	19
<b>KNLC</b>			Lemoore NAS / Reeves Fld
		SID	
		LEM2EO	40
		REV5BU	40
<b>KPAM</b>			Panama City/Tyndall AFB
		APCH	
		T14LY	19
		T14LZ	19
		T14RY	19
		T32LY	19
		T32RY	19
		T32RZ	19
<b>KTCM</b>			Tacoma/McChord Fld /Joint Bas
		STAR	
		WHYTE7	40
<b>KVPS</b>			Valparaiso/Destin-Ft Walton Be
		APCH	
		T02	19
		T12	19
		T20	19
		T30	19
<b>KWAL</b>			Wallops Island/Wallops Flight
		APCH	
		T10	41
<b>KWRB</b>			Warner Robins/Robins AFB
		APCH	
		T15-Y	19
		T15-Z	19
		T33-Y	19
		T33-Z	19
<b>LEZG</b>			Zaragoza
		APCH	
		T12RZ	19
		T30RZ	19

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>LJCE</b>			Cerklje ob Krki
	APCH	N08	22
<b>MMAN</b>			Monterrey/Del Norte Intl
	APCH	V20-W	11
<b>NZWB</b>			Woodbourne
	STAR	NORTHV	27
		WESTV	27
<b>OPKC</b>			Karachi/Jinnah Intl
	APCH	V25LY	3
		V25RY	3
<b>OPLA</b>			Lahore/Allama Iqbal Intl
	APCH	V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
<b>PAAD</b>			Deadhorse/Point Thomson Airstr
	APCH	R05	40
		R23	40
<b>PABP</b>			Deadhorse/Badami
	APCH	R04	40
		R22	40
<b>PACZ</b>			Cape Romanzof LRRS
	APCH	R02	40
<b>PADG</b>			Red Dog
	APCH	R03	40
		R03-P	40
	SID	SICOV1	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>PADK</b>			Adak Island/Adak
	APCH	R23-N	40
<b>PADQ</b>			Kodiak
	APCH	I26-Z	40
		L26-Z	40
<b>PADU</b>			Unalaska
	APCH	N13	40
		N31	40
		R13	40
		R13-M	40
		R31	40
		R31-M	40
	SID	DUT1	40
<b>PAGB</b>			Galbraith Lake
	APCH	R14	40
	SID	ARTIC2	40
<b>PAIM</b>			Utopia Creek/Indian Mountain L
	APCH	N25	40
		R25	40
	SID	CLYDD4	40
<b>PAJN</b>			Juneau Intl
	APCH	R08-T	40
<b>PAKU</b>			Kuparuk/Ugnu-Kuparuk
	APCH	I06	40
		I24	40
		L06	40
		L24	40
		R06	40
		R24	40

\*See Reason Code table on page R1

	Type	Procedure	Reason*
<b>PAKW</b>			Klawock
	APCH	R02-Z	40
<b>PALP</b>			Nuiqsut/Alpine Airstrip
	APCH	R04	40
		R22	40
	SID	NUQST1	40
<b>PALU</b>			Cape Lisburne LRRS
	APCH	R27	40
	SID	GRAAY4	40
		LUR8	40
<b>PAPG</b>			Petersburg James A Johnson
	APCH	R23-P	40
<b>PAPR</b>			Prospect Creek
	APCH	R01-M	40
		R01-Z	40
		R19	40
	SID	CYCLE1	40
<b>PASV</b>			Sparrevohn LRRS
	APCH	N35	40
		R35	40
<b>PATC</b>			Tin City LRRS
	APCH	Q35	40
		R35	40
	SID	HONPO3	40
		JEKLI3	40
		TNC5	40

\*See Reason Code table on page R1

Type	Procedure	Reason*
<b>PATL</b>		Takotna/Tatalina LRRS
	APCH	
	R35	40
	SID	
	TLJ4	40
<b>PAVD</b>		Valdez Pioneer Fld
	SID	
	FJORD1	40
	JOH2	40
<b>RJBB</b>		Kansai Intl
	STAR	
	CDO1	42
	CDO2F	42
	CDO20	42
	CDO3	42
	CDO4	42
<b>RKSM</b>		Seoul Domestic
	APCH	
	I20	22
	I20-Z	22
	L19	22
	L19-Z	22
	L20	22
	L20-Z	22
<b>RKSO</b>		Songtan-Si/Osan AB
	APCH	
	T09LZ	19
	T09RZ	19
	T27LZ	19
	T27RZ	19
<b>TX25</b>		Athens/Lochridge Ranch
	APCH	
	N17	40
<b>UNSS</b>		Strezhevoy
	SID	
	BUNA1Z	22
<b>VTBK</b>		Nakhon Pathom/Kamphaeng Saen
	APCH	
	V21	2

\*See Reason Code table on page R1

## Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
40	Procedure requires special authorization
41	AF leg in final
42	Profile descent STARS

If you have any questions concerning this report, please contact your FMS Customer Support at [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com) or call +41 44 828 65 55