

Procedures removed from ARINC output Cycle 2608

	Type	Procedure	Transition	Reason
AYKV				Kavieng
		APCH		
		R30	YKVED	Notam AY A1069/22 THR RWY 30 coordinates changed
		R30	YKVEE	Notam AY A1069/22 THR RWY 30 coordinates changed
		R30	YKVEG	Notam AY A1069/22 THR RWY 30 coordinates changed
		R30		Notam AY A1069/22 THR RWY 30 coordinates changed
DAUB				Biskra / Mohamed Khider
		APCH		
		I31	BIS	RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
		I31		RWY has been extended to the southeast by 200m, but procedure has not been amended accordingly.
DNKS				Kashimbila
		APCH		
		H13	IVGIR	ALT published on final not correct - DN AIRAC AMDT 03/2026
		H13	XUMSO	ALT published on final not correct - DN AIRAC AMDT 03/2026
		H13		ALT published on final not correct - DN AIRAC AMDT 03/2026
		H31	EBTEM	ALT published on final not correct - DN AIRAC AMDT 03/2026
		H31		ALT published on final not correct - DN AIRAC AMDT 03/2026

	Type	Procedure	Transition	Reason
DNMN				Minna
		APCH		
		I05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		I05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		L05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		L05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V05	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V05		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V23	MNA	MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
		V23		MNA VOR/DME moved, but affected procedures not updated. PBN approaches remain valid.
EGVN				Brize Norton AB
		SID		
		ALPHA	RW07	Different Endfixes not possible
		ALPHA	RW25	Different Endfixes not possible
		BRAVO	RW07	Different Endfixes not possible
		BRAVO	RW25	Different Endfixes not possible
FMMS				Sainte Marie
		APCH		
		N01	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N01		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N19	SM	ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD
		N19		ASECNA SUP 22/A/25FM: USE OF 'NDB-RWY 01' AND 'NDB-RWY 19' IAP PROHIBITED DUE TO NEW NDB COORD

	Type	Procedure	Transition	Reason
FNLU	Luanda / 4th of February			
	APCH			
	I23		ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	I23		R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	I23			FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23		ONTAR	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
	L23		R080L	FN AMDT 01/23 (eff. Nov 2nd 2023) procedure withdrawal and NAVAID declination update unclear.
FZKA	Bunia			
	APCH			
	R09		PESUX	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R09		UXIMO	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R09		VEBID	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R09			NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27		ABGAX	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27		EKLIT	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27		IDMED	NOTAM FZ B0064/2026 updated the RWY coordinates.
	R27			NOTAM FZ B0064/2026 updated the RWY coordinates.
FZMA	Bukavu / Kavumu			
	APCH			
	R35		DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35			Incorrect Source: AIRAC AIP SUP S3006/06

	Type	Procedure	Transition	Reason
HKLK				Lokichoggio
	APCH			
		H27	EPSUT	HK Notam B0002/21
		H27		HK Notam B0002/21
HLLT				Tripoli Intl
	STAR			
		IZD1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
		SINA1A	RW09	HL SUP 01/2026 and NOTAM (HL A0108/25 PERM)
KLCK				Columbus / Rickenbacker Intl, OH
	APCH			
		R05L	GAILL	
		R05L	HIGID	
		R05L	TARTO	
		R05L		not trusted due to calc. angle of 3.16°
OAKB				Kabul Intl
	SID			
		TAPIS2	RW11	RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)
	APCH			
		R29		RNAV waypoint coordinates are no longer published (neither in state source not in DAFIF)
SVRS				El Gran Roque Natl
	APCH			
		H25	ANLEG	SV AIRAC SUP C 03/A03 2026
		H25	TOROP	SV AIRAC SUP C 03/A03 2026
		H25		SV AIRAC SUP C 03/A03 2026

Type	Procedure	Transition	Reason
UERP	Poliarny		
	SID		
	ABNI1F	RW36	NTM UE C3683/25 (proc not to be used)
	BAGO1F	RW36	NTM UE C3683/25 (proc not to be used)
	BALU1F	RW36	NTM UE C3683/25 (proc not to be used)
	DEDO1F	RW36	NTM UE C3683/25 (proc not to be used)
	FADR1F	RW36	NTM UE C3683/25 (proc not to be used)
	GILA1F	RW36	NTM UE C3683/25 (proc not to be used)
	INDI1F	RW36	NTM UE C3683/25 (proc not to be used)
	NERD1F	RW36	NTM UE C3683/25 (proc not to be used)
	OGON1F	RW36	NTM UE C3683/25 (proc not to be used)
	PELI1F	RW36	NTM UE C3683/25 (proc not to be used)
	PIRO1F	RW36	NTM UE C3683/25 (proc not to be used)
	RUSE1F	RW36	NTM UE C3683/25 (proc not to be used)
	SUGI1F	RW36	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
STAR			
	ABNI1L	RW18	NTM UE C3683/25 (proc not to be used)
	ABNI1L	RW36	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW18	NTM UE C3683/25 (proc not to be used)
	BAGO1L	RW36	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW18	NTM UE C3683/25 (proc not to be used)
	BALU1L	RW36	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW18	NTM UE C3683/25 (proc not to be used)
	DEDO1L	RW36	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW18	NTM UE C3683/25 (proc not to be used)
	FADR1L	RW36	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW18	NTM UE C3683/25 (proc not to be used)
	GILA1L	RW36	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW18	NTM UE C3683/25 (proc not to be used)
	INDI1L	RW36	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW18	NTM UE C3683/25 (proc not to be used)
	NERD1L	RW36	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW18	NTM UE C3683/25 (proc not to be used)
	OGON1L	RW36	NTM UE C3683/25 (proc not to be used)
	PELI1L	RW18	NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
	PELI1L	RW36	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW18	NTM UE C3683/25 (proc not to be used)
	PIRO1L	RW36	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW18	NTM UE C3683/25 (proc not to be used)
	RUSE1L	RW36	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW18	NTM UE C3683/25 (proc not to be used)
	SUGI1L	RW36	NTM UE C3683/25 (proc not to be used)
APCH			
	J18	RP003	NTM UE C3298/24
	J18	RP004	NTM UE C3298/24
	J18		NTM UE C3298/24
	V18	PLR	NTM UE C3683/25 (proc not to be used)
	V18		NTM UE C3683/25 (proc not to be used)
	V36	PLR	NTM UE C3683/25 (proc not to be used)
	V36		NTM UE C3683/25 (proc not to be used)

Type	Procedure	Transition	Reason
UUOO	Voronezh / Chertovitskoye		
	APCH		
	J30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	J30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-U		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	A	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V	AHI	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	N30-V		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30	OO303	U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
	R30		U NOTAM A5869/2024 LDG threshold RW30 displ by 300m. Only VFR apchs.
VLVT	Vientiane / Wattay Intl		
	SID		
	BIK1C	RW31	Lao AIRAC SUP A04/25 - WEF 30 OCT 2025. Mismatch between graphical depiction and procedure text