

## Navigation Database Addendum

### **AIRAC 2503 – Correction issue 16**

**AMDT ED 03/25 effective 20th March 2025**

### **EDDH Hamburg**

---

Due to late publication by AMDT 03/25 following changes for EDDH are not reflected in FMS database.

- ILS or LOC RWY 05: Speed at IAF DH257 **at 220 KT.**
- ILS or LOC RWY 15: Speed at IAF DH457 **at 220 KT.**  
MISAP ALT at HAM reads **4000 ft.**
- **RNP RWY 05: Speed at IAF DH257 at 220 KT.**
- **RNP RWY 15: Speed at IAF DH457 at 220 KT. Speed at DH413 at 220 KT.**  
MISAP ALT at HAM reads **at 4000 ft.**
- **RNP RWY 23: Speed at IAF DH657 at 220 KT.**
- **RNP RWY 33: Speed at IAF DH857 at 220 KT.**  
MISAP ALT at HAM reads **at 4000 ft.**

Navdata will be updated effective AIRAC cycle 2504.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Friday, 21<sup>st</sup> March 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)