

Navigation Database Addendum

AIRAC 2507 – Issue 5

SUP SK 20/25 effective 10th July 2025

SKVV Villavicencio Vanguardia

SID NIPNO 2A

Due to late receipt of document, following speed restrictions are not updated in the NavDB:

- Transition BUTIK - no speed at BUTIK
- Transition DANSA - no speed at SALGU
- Transition ROPOR - speed at VV906 should read "max. 180KT"
- Transition VUNEX - no speed at SALGU

Navdata will be updated effective AIRAC cycle 2508.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 26th June 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com