

Navigation Database Addendum

AIRAC 2507 – Issue 12

AIRAC AMDT RP 001/25 effective 10th July 2025

RPMY Cagayan de Oro Laguindingan Airport

Waypoints MAURI / NADUM / SIKIN

Following waypoint ident's are not up-to-date in the NavDB:

- MORSO shall read MAURI in:
 - o SID's MAURI 5A / MAURI 7A.
 - o STAR's MAURI 2C / MAURI 4A / MAURI 6A.
- NUMBI shall read NADUM in:
 - o SID's NADUM 5A / NADUM 7A.
 - o STAR's NADUM 2C / NADUM 4A / NADUM 6A.
- SAKIB shall read SIKIN in:
 - o SID's SIKIN 5A / SIKIN 7A.
 - o STAR's SIKIN 2C / SIKIN 4A / SIKIN 6A.

Waypoint coordinates remain the same.

Navdata will be updated effective AIRAC cycle 2508.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 8th July 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com