

Navigation Database Addendum

AIRAC 2507 – Issue 15

NOTAM B5192/25 effective 10th July 2025

LEXJ Santander Seve Ballesteros-Santander

SID TITAN 7A; Runway 29

SID TITAN 7A, WPT **KURUK** at or above 6000 ft missing in procedure, routing should read "...R186I, **KURUK at or above 6000 ft**, TITAN at or above FL100."

Navdata will be updated effective AIRAC cycle 2508.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Freitag, 11th July 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com