



Navigation Database Addendum

Tuesday, 26 August 2025

AIRAC 2509 – Issue 6

Source: SUP 127/25, Effective date: 04 September 2025

RJAA Narita Intl

Holding: BOSPA

Inbound track for BOSPA holdings for procedures mentioned below, should read **314°**.

Affected procedures: ILS 16LX, ILS 16LY, ILS 16LZ, LOC 16LX, LOC 16LY, LOC 34R, ILS 34RY, ILS 34RZ.

Navdata will be updated effective AIRAC cycle 2510.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com