



Navigation Database Addendum

Monday, 24 November 2025

AIRAC 2512 – Issue 10

EY SUP 12/2025

EYVI Vilnius Intl

Effective 27 NOV 2025 until 01 DEC 2025, due to SUP 12/2025 expiring outside AIRAC cycle effective date, the following procedures are not updated in database:

RNP RWY 01, **MISAP should read**: climb on RWY track (014°) to 5000 FT - radar vectoring will be provided.

IAC ILS Z RWY 01, **MISAP should read**: climb on RWY track (014°) to 5000 FT - radar vectoring will be provided.

RNP RWY 19, **MISAP should read**: climb on RWY track (194°) to 5000 FT - radar vectoring will be provided.

IAC ILS Z RWY 19, **MISAP should read**: climb on RWY track (194°) to 5000 FT - radar vectoring will be provided.

Following procedures are **not available**, expect ATC instructions:

SID RWY 01 DUKAT 1A, LAFAT 1A and SID RWY 19 DUKAT 1B, LAFAT 1B.

STAR RWY 01 DUKAT 2A, LAFAT 2A and STAR RWY 19 DUKAT 2B, LAFAT 2B.

Holding over IAF EKSAM, INSOL.

Please disseminate this information to all affected crews.

Lufthansa Systems
FMS Customer Support

All valid NDAs are available on <https://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com