

## Procedures removed from ARINC output Cycle 1907

| Type        | Procedure | Transition | Reason  |
|-------------|-----------|------------|---|
| <b>3S8_</b> |           |            | Grants Pass, OR                                     |
|             | APCH      |            |   |
|             | R13       | CAMAS      | published angle not coincident with calculated one. |
|             | R13       |            | published angle not coincident with calculated one. |
| <b>CPZ3</b> |           |            | Trenton / Mountain View, ON                         |
|             | APCH      |            |   |
|             | R06R      | LEPAP      | source inconsistency, not published in CAP/RCAP     |
|             | R06R      | SEGEP      | source inconsistency, not published in CAP/RCAP     |
|             | R06R      | ZASER      | source inconsistency, not published in CAP/RCAP     |
|             | R06R      |            | source inconsistency, not published in CAP/RCAP     |
|             | R24L      | ALIRA      | source inconsistency, not published in CAP/RCAP     |
|             | R24L      | GADEN      | source inconsistency, not published in CAP/RCAP     |
|             | R24L      | ODBAK      | source inconsistency, not published in CAP/RCAP     |
|             | R24L      |            | source inconsistency, not published in CAP/RCAP     |
| <b>DGLE</b> |           |            | Tamale  |
|             | APCH      |            |   |
|             | V05-Y     | TLE        | NOTAM B033/16 - THR 05 displaced                    |
|             | V05-Y     |            | NOTAM B033/16 - THR 05 displaced                    |
|             | V05-Z     | R140J      | NOTAM B033/16 - THR 05 displaced                    |
|             | V05-Z     | R320J      | NOTAM B033/16 - THR 05 displaced                    |
|             | V05-Z     | TLE        | NOTAM B033/16 - THR 05 displaced                    |
|             | V05-Z     |            | NOTAM B033/16 - THR 05 displaced                    |

| Type        | Procedure       | Transition                      | Reason                          |
|-------------|-----------------|---------------------------------|---------------------------------|
| <b>EGVN</b> | Brize Norton AB |                                 |                                 |
|             | SID             |                                 |                                 |
|             | ALPHA           | RW07                            | Different Endfixes not possible |
|             | ALPHA           | RW25                            | Different Endfixes not possible |
|             | BRAVO           | RW07                            | Different Endfixes not possible |
| BRAVO       | RW25            | Different Endfixes not possible |                                 |

|             |                 |  |  |
|-------------|-----------------|--|--|
| <b>FZMA</b> | Bukavu / Kavumu |  |  |
|             | APCH            |  |  |
|             | R35             | DOPEM                                    | Incorrect Source: AIRAC AIP SUP S3006/06 |
|             | R35             | OSLON                                    | Incorrect Source: AIRAC AIP SUP S3006/06 |
|             | R35             | Incorrect Source: AIRAC AIP SUP S3006/06 |  |

|             |           |               |               |
|-------------|-----------|---------------|---------------|
| <b>FZNA</b> | Goma Intl |               |               |
|             | APCH      |               |               |
|             | R35       | NESOG         | Unsafe Source |
|             | R35       | OLIKO         | Unsafe Source |
|             | R35       | RIXAR         | Unsafe Source |
|             | R35       | Unsafe Source |               |

| Type        | Procedure | Transition | Reason  |
|-------------|-----------|------------|---|
| <b>HLLT</b> |           |            | Tripoli Intl  |
|             | SID       |            |   |
|             | GARU1C    | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | GRT1C     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | GRT1G     | RW27       | VOR/DME TPI new coordinates, procedures not updated |
|             | IZD1C     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | IZD1G     | RW27       | VOR/DME TPI new coordinates, procedures not updated |
|             | MIS1C     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | MIS1G     | RW27       | VOR/DME TPI new coordinates, procedures not updated |
|             | SARK1C    | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | SINA1C    | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | SINA1G    | RW27       | VOR/DME TPI new coordinates, procedures not updated |
|             | WLD1C     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | STAR      |            |   |
|             | GRT1A     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | GRT1E     | RW27       | VOR/DME TPI new coordinates, procedures not updated |
|             | IZD1A     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | IZD1E     | RW27       | VOR/DME TPI new coordinates, procedures not updated |
|             | MIS1A     | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | SINA1A    | RW09       | VOR/DME TPI new coordinates, procedures not updated |
|             | SINA1E    | RW27       | VOR/DME TPI new coordinates, procedures not updated |

| Type        | Procedure | Transition | Reason   |
|-------------|-----------|------------|--|
| <b>HSSJ</b> |           |            | Juba   |
|             | APCH      |            |  |
|             | R13       | ALSAP      | runway extended, procedure not updated   |
|             | R13       | ALSOG      | runway extended, procedure not updated   |
|             | R13       | RALSA      | runway extended, procedure not updated   |
|             | R13       |            | runway extended, procedure not updated   |
| <b>KCLR</b> |           |            | Calipatria / Cliff Hatfield Mem, CA  |
|             | APCH      |            |  |
|             | R08       | BOREN      |  |
|             | R08       |            |  |
| <b>KEUG</b> |           |            | Eugene / Mahlon Sweet Fld, OR  |
|             | APCH      |            |  |
|             | R34LZ     | DRAIN      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34LZ     | SHEDD      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34LZ     | VAUGN      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34LZ     | VIDAS      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34LZ     |            | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34RZ     | SAGIN      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34RZ     | SHEDD      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34RZ     | VAUGN      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34RZ     | VIDAS      | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |
|             | R34RZ     |            | FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ. |

| Type        | Procedure | Transition | Reason  |
|-------------|-----------|------------|---|
| <b>KLCK</b> |           |            | Columbus / Rickenbacker Intl, OH  |
|             | APCH      |            |   |
|             | R05L      | GAILL      |   |
|             | R05L      | HIGID      |   |
|             | R05L      | TARTO      |   |
|             | R05L      |            | not trusted due to calc. angle of 3.16°   |
| <b>KTYS</b> |           |            | Knoxville / Mc Ghee Tyson, TN   |
|             | APCH      |            |   |
|             | I23R      | NEYLN      | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | I23R      |            | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | L23R      | NEYLN      | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | L23R      |            | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | R23R      | NEYLN      | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | R23R      |            | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | V23R      | VXV        | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
|             | V23R      |            | RWY shortened by 3004 ft acc. NFDD 176/2105, procedures suspended by NOTAM FDC 5/7765, A1567/15 |
| <b>LGEL</b> |           |            | Elefsis   |
|             | APCH      |            |   |
|             | V36LA     | R219N      | Unclear source  |
|             | V36LA     |            | Unclear source  |

| Type        | Procedure | Transition | Reason                              |
|-------------|-----------|------------|-------------------------------------|
| <b>LRSV</b> |           |            | Suceava / Stefan cel Mare - Suceava |
|             | APCH      |            |                                     |
|             | R16       | BUKOV      | FAS DB not provided                 |
|             | R16       | HUMOR      | FAS DB not provided                 |
|             | R16       | PASKA      | FAS DB not provided                 |
|             | R16       | TOMUC      | FAS DB not provided                 |
|             | R16       |            | FAS DB not provided                 |
|             | R34       | BUKOV      | FAS DB not provided                 |
|             | R34       | HUMOR      | FAS DB not provided                 |
|             | R34       | PASKA      | FAS DB not provided                 |
|             | R34       | RIVKA      | FAS DB not provided                 |
|             | R34       | TOMUC      | FAS DB not provided                 |
|             | R34       |            | FAS DB not provided                 |

|             |       |     |  |
|-------------|-------|-----|--|
| <b>SBGW</b> |       |     | Guaratingueta, SP                              |
|             | APCH  |     |  |
|             | N02-A | GGT | procedure not compatibel with FMS requirements |
|             | N02-A |     | procedure not compatibel with FMS requirements |
|             | N20-B | GGT | procedure not compatibel with FMS requirements |
|             | N20-B |     | procedure not compatibel with FMS requirements |

|             |       |     |   |
|-------------|-------|-----|---|
| <b>SKQU</b> |       |     | Mariquita / Jose Celestino Mutis  |
|             | APCH  |     |   |
|             | V01-A | MQU | circling apch not leading to RWY, final track offset by more than 15 DEG. |
|             | V01-A |     | circling apch not leading to RWY, final track offset by more than 15 DEG. |

| Type        | Procedure | Transition | Reason                                   |
|-------------|-----------|------------|--|
| <b>VYPN</b> |           |            | Pathein                                  |
|             | APCH      |            |  |
|             | V06       | PTN        | repositioning of PTN VORDME, AMDT 1/2016 |
|             | V06       |            | repositioning of PTN VORDME, AMDT 1/2016 |
|             | V24       | PTN        | repositioning of PTN VORDME, AMDT 1/2016 |
|             | V24       |            | repositioning of PTN VORDME, AMDT 1/2016 |
| <b>WAPP</b> |           |            | Ambon / Pattimura                        |
|             | APCH      |            |  |
|             | R22       |            | no RF Center Fix published               |