

Exclusion List for GE NavDBs in Cycle 2010

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 2010. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
SID		
	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5

EBBL

Kleine Brogel

SID

	BL05A	22
	BL05B	22
	BL05D	22

EBFS

Florennes

SID

	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

EGHC

Penzance/Lands End

APCH

	R07	5
	R16	5
	R25	5
	R34	5

EGHE

St Mary's/Scilly Isles

APCH

	N27	5
	N32	5

EGJA

St Annes/Alderney

APCH

	N08	5
	N26	5

EGYD

Cranwell

SID

	SID1B	5
--	-------	---

EHEH

Eindhoven

SID

	EH5	22
--	-----	----

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J04	1
		J22	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

Type	Procedure	Reason*
ENRM		Rorvik/Ryum
	APCH	
	J04	1
	J22	1
ENRS		Rost
	APCH	
	J02	1
	J20	1
ENSH		Svolvaer/Helle
	APCH	
	J01	1
ENSK		Stokmarknes/Skagen
	APCH	
	J09	1
ENSS		Vardo/Svartnes
	APCH	
	J15	1
	J33	1
ENST		Stokka/Sandnessjoen
	APCH	
	J02	1
	J20	1
ENVD		Vadso
	APCH	
	J07	1
	J25	1
EPPR		Pruszcz Gdanski
	APCH	
	N27-X	5
	N27-Y	5
	N27-Z	5
ETHB		Buckeburg
	SID	
	HB11	5
	HB12	5
	HB13	5
	HB31	5
	HB32	5
HB33	5	

*See Reason Code table on page R1

	Type	Procedure	Reason*
ETNG			Geilenkirchen
		SID	
		NG13	11
		NG227	22
		NG33	22
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
GVSV			Sao Pedro/Sao Vicente/Cesaria
		SID	
		SNT1G	22
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5
KMTN			Baltimore/Martin State
		APCH	
		T15	31
		V15	31
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
LFBD			Bordeaux/Merignac
		SID	
		ROYA4Z	5
		SAU4Z	5
		VAVI4Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
LHPA			Papa AB
	APCH		
		N16	5
LIMS			Piacenza
	SID		
		GEN6Q	22
		KALM6Q	22
MRLB			Liberia/Daniel Oduber Quiros I
	APCH		
		V07	2
MSSS			San Salvador/Ilopango Intl
	APCH		
		V15	5
N07			Lincoln Park
	APCH		
		R01	5
		R19	5
N40			Pittstown/Sky Manor
	APCH		
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
	APCH		
		D08	5
NTAA			Tahiti/Faa'a
	SID		
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
	SID		
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
	APCH		
		V27-X	5
NZTK			Takaka
	APCH		
		R18-Y	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OERR			Arar Domestic
		APCH	
		V10	2
PARS			Russian Mission
		APCH	
		R36	5
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
SBFZ			Fortaleza/Pinto Martins Intl
		APCH	
		V31	2
SKUL			Tulua/Heriberto Gil Martinez
		APCH	
		V02	5
UHPK			Ust-Kamchatsk
		STAR	
		DOMUD2	5
UIUU			Ulan-Ude/Mukhino
		APCH	
		I08-Y	5
		N08-Y	5
		N08-Z	5
		STAR	
		BULE5H	5
		OSTU5H	5
		RIDL5H	5
	TOLG5H	5	

*See Reason Code table on page R1

	Type	Procedure	Reason*
UKHK			Kremenchuk/Velyka Kokhnyvka Na
	APCH	N36	5
URRT			Taganrog/Yuzhny
	APCH	N10-X	5
		N28-X	5
UWGG			Nizhny Novgorod/Strigino
	APCH	J18L	1
		J36R	1
VTBK			Nakhon Pathom/Kamphaeng Saen
	APCH	V21	2
WAJI			Sarmi/Orai
	APCH	R13	5
WAKE			Bade
	APCH	R02	5
		R20	5
WASA			Ayawasi
	APCH	R09	5
		R27	5
WASI			Inanwatan
	APCH	R08	5
		R26	5
WAUM			Merdei/Jahabra
	APCH	R27	5
WAYK			Kokonao
	APCH	H13	5
WIRR			Tangerang/Budiarto
	APCH	V30	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
ZGSD			Zhuhai/Jinwan
	STAR		
		F02A	22
ZYTX			Shenyang/Taoxian
	STAR		
		ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
31	procedure contains AF (Arc-to-Fix) Path Termination in final approach coding

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55