

Exclusion List for GE NavDBs in Cycle 2101

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to GE Aviation for AIRAC cycle 2101. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (GE Aviation).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5

*See Reason Code table on page R1

Type Procedure Reason*

SID

BE04C 5

BE04D 5

BE22C 5

BE22D 5

EBBL

Kleine Brogel

SID

BL05A 22

BL05B 22

BL05D 22

EBFS

Florennes

SID

FS08A 22

FS08B 22

FS08C 22

FS26A 22

FS26B 22

FS26C 22

EGHC

Penzance/Lands End

APCH

H07 5

H16 5

H25 5

H34 5

EGHE

St Mary's/Scilly Isles

APCH

N27 5

N32 5

EGJA

St Annes/Alderney

APCH

N08 5

N26 5

EGYD

Cranwell

SID

SID1B 5

EHEH

Eindhoven

SID

EH5 22

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J04	1
		J22	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENMS			Mosjoen/Kjaerstad
		APCH	
		J34	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSK			Stokmarknes/Skagen
		APCH	
		J09	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETNG			Geilenkirchen
		SID	
		NG13	11
		NG227	22
		NG33	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5
KMTN			Baltimore/Martin State
		APCH	
		T15	31
		V15	31
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
LFBD			Bordeaux/Merignac
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5
LHPA			Papa AB
		APCH	
		N16	5
LIMS			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
MMTO			Toluca/Lic Adolfo L Mateos Int
		APCH	
		H15	13
		H33	13
MPRA			Contadora/Cnel. Raul Arias Esp
		APCH	
		R18	5
MRLB			Liberia/Daniel Oduber Quiros I
		APCH	
		V07	2
MSSS			San Salvador/Ilopango Intl
		APCH	
		V15	5
N07			Lincoln Park
		APCH	
		R01	5
		R19	5
N40			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
		APCH	
		D08	5
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NZWB			Woodbourne
	STAR		
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
	APCH		
		V28	2
OERR			Arar Domestic
	APCH		
		V10	2
PARS			Russian Mission
	APCH		
		R36	5
RKSM			Seoul Domestic
	APCH		
		I20-Z	22
		L19-Z	22
		L20-Z	22
SBFZ			Fortaleza/Pinto Martins Intl
	APCH		
		V31	2
SKUL			Tulua/Heriberto Gil Martinez
	APCH		
		V02	5
UHPK			Ust-Kamchatsk
	STAR		
		DOMUD2	5
UIUU			Ulan-Ude/Mukhino
	APCH		
		I08-Y	5
		N08-Y	5
		N08-Z	5
	STAR		
		BULE5H	5
		OSTU5H	5
		RIDL5H	5
	TOLG5H	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
URML		Makhachkala/Uytash
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
URRT		Taganrog/Yuzhny
	APCH	
	N10-X	5
	N28-X	5
UWKD		Kazan
	APCH	
VTBK		Nakhon Pathom/Kamphaeng Saen
	APCH	
WAJI		Sarmi/Orai
	APCH	
WAKE		Bade
	APCH	
	R02	5
WASA		Ayawasi
	APCH	
	R09	5
WASI		Inanwatan
	APCH	
	H08	5
WAUM		Merdei/Jahabra
	APCH	
	R27	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
WAYK			Kokonao
		APCH	
		H13	5
WIRR			Tangerang/Budiarto
		APCH	
		V30	5
ZYTX			Shenyang/Taoxian
		STAR	
		ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table GE

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix
31	procedure contains AF (Arc-to-Fix) Path Termination in final approach coding

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55