

Exclusion List for HWL NavDBs in Cycle 2110

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2110. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I22RX	5
	I22RY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
T22L	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
SID		
	BE04C	5
	BE04D	5
	BE22C	5
	BE22D	5

EBBL

Kleine Brogel

SID

	BL05A	22
	BL05B	22
	BL05D	22

EBFS

Florennes

SID

	FS08A	22
	FS08B	22
	FS08C	22
	FS26A	22
	FS26B	22
	FS26C	22

EGHC

Penzance/Lands End

APCH

	H07	5
	H16	5
	H25	5
	H34	5

EGHE

St Mary's/Scilly Isles

APCH

	N27	5
	N32	5

EGJA

St Annes/Alderney

APCH

	N08	5
	N26	5

EGNH

Blackpool

APCH

	N10	3
--	-----	---

EGNV

Teesside International

APCH

	N23	3
--	-----	---

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGPO			Stornoway
		APCH	
		L36	3
		N36	3
EGTE			Exeter
		APCH	
		N26	3
EGYD			Cranwell
		SID	
		SID1B	5
EHEH			Eindhoven
		SID	
		EH5	22
ENBL			Forde/Bringeland
		APCH	
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
		APCH	
		J03	1
ENBS			Batsfjord
		APCH	
		J03	1
		J21	1
ENBV			Berlevag
		APCH	
		J06	1
		J24	1
ENHF			Hammerfest
		APCH	
		J04	1
		J22	1
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVD			Vadso
		APCH	
		J07	1
		J25	1
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETNG			Geilenkirchen
		SID	
		NG227	22

*See Reason Code table on page R1

	Type	Procedure	Reason*
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
HLLM			Tripoli/Mitiga Intl
		APCH	
		D10	2
		D28	2
KDLH			Duluth Intl
		APCH	
		T09	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T34-W	19
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18	19
		T36	19
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5
KLSV			Las Vegas/Nellis AFB
		APCH	
		T21LX	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
KMTN			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
LFBD			Bordeaux/Merignac
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5
LHPA			Papa AB
		APCH	
		N16	5
LIMS			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
MHTG			Tegucigalpa/Toncontin Intl
		APCH	
		H20	13

*See Reason Code table on page R1

	Type	Procedure	Reason*
MRLB			Liberia/Daniel Oduber Quiros I
	APCH	V07	2
MSSS			San Salvador/Ilopango Intl
	APCH	V15	5
N07			Lincoln Park
	APCH	R01	5
		R19	5
N40			Pittstown/Sky Manor
	APCH	R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
	APCH	D08	5
NTAA			Tahiti/Faa'a
	SID	ARIT4E	5
		ARIT4W	5
NTTE			Tetiaroa
	SID	TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
	APCH	V27-X	5
NZTK			Takaka
	APCH	R18-Y	5
NZWB			Woodbourne
	STAR	NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
	APCH	V28	2

*See Reason Code table on page R1

	Type	Procedure	Reason*
OERR			Arar Domestic
		APCH	
		V10	2
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
	V36R	3	
OPRK			Rahim Yar Khan/Sheikh Zayed In
		APCH	
		V01	3
PARS			Russian Mission
		APCH	
		R36	5
RJNH			Hamamatsu
		APCH	
		T09-1	19
		T09-3	19
		T09-5	19
		T27-2	19
		T27-4	19
	T27-6	19	
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
	L20-Z	22	
SKUL			Tulua/Heriberto Gil Martinez
		APCH	
		V02	5
UHHM			Chegdomyn
		APCH	
		H13	5
	H31	5	
UHPK			Ust-Kamchatsk
		STAR	
		DOMUD2	5

*See Reason Code table on page R1

Type	Procedure	Reason*
UIUU		Ulan-Ude/Mukhino
	APCH	
	I08-Y	5
	N08-Y	5
	N08-Z	5
	STAR	
	BULE5H	5
	OSTU5H	5
	RIDL5H	5
	TOLG5H	5
UKHK		Kremenchuk/Velyka Kokhivka
	APCH	
	N36	5
URML		Makhachkala/Uytash
	SID	
	H1A	5
	TA1A	5
	STAR	
	BUIK1E	5
	BUIK1G	5
	GUDE1E	5
	GUDE1G	5
URRT		Taganrog/Yuzhny
	APCH	
	N10-X	5
	N28-X	5
UWKD		Kazan
	APCH	
	V11-X	5
UWSK		Krasny Kut
	SID	
	X003	5
	X070	5
	X107	5
	X130	5
	X156	5
	X267	5
	X312	5
	X351	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
VTBK			Nakhon Pathom/Kamphaeng Saen
	APCH	V21	2
WAJI			Sarmi/Mararena
	APCH	H13	5
		H31	5
WAKE			Mappi/Bade
	APCH	H02	5
		H20	5
WASA			Maybrat/Ayawasi
	APCH	H09	5
		H27	5
WASI			Inanwatan
	APCH	H08	5
		H26	5
WAUM			Merdey
	APCH	H27	5
WAYK			Kokonao
	APCH	H13	5
WIRR			Tangerang/Budiarto
	APCH	V30	5
ZYTX			Shenyang/Taoxian
	STAR	ANS02A	22
		TOS02A	22

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55