

Exclusion List for HWL NavDBs in Cycle 2204

Listed below are all terminal procedures that are removed from the ARINC 424 file provided to Honeywell for AIRAC cycle 2204. This list does not compromise procedures or other data that have been removed during processing by the Data Packer (Honeywell).

Type	Procedure	Reason*
06N		Middletown/Randall
	APCH	
	R08	5
	R26	5
012		Brazil Clay County
	APCH	
	R27	5
12N		Andover/Aeroflex-Andover
	APCH	
	R03	5
2W2		Westminster/Clairview Airpark
	APCH	
	R14	5
9A5		Lafayette/Barwick Lafayette
	APCH	
	R02	5
	R20	5
CYYT		St Johns Intl
	APCH	
	R11-X	5
	R16-X	5
EBBE		Beauvechain
	APCH	
	I04LY	5
	I22RX	5
	I22RY	5
	L04LY	5
	L22RX	5
	L22RY	5
	T04LY	5
	T04R	5
	T22L	5
T22RY	5	

*See Reason Code table on page R1

Type	Procedure	Reason*
------	-----------	---------

SID		
-----	--	--

	BE04C	5
--	-------	---

	BE04D	5
--	-------	---

	BE22C	5
--	-------	---

	BE22D	5
--	-------	---

EBBL

Kleine Brogel

APCH

	T05R	5
--	------	---

	T23L	5
--	------	---

SID

	BL05A	22
--	-------	----

	BL05B	22
--	-------	----

	BL05D	22
--	-------	----

EBFS

Florennes

SID

	FS08A	22
--	-------	----

	FS08B	22
--	-------	----

	FS08C	22
--	-------	----

	FS26A	22
--	-------	----

	FS26B	22
--	-------	----

	FS26C	22
--	-------	----

EGHC

Penzance/Land s End

APCH

	H07	5
--	-----	---

	H16	5
--	-----	---

	H25	5
--	-----	---

	H34	5
--	-----	---

EGHE

St Mary's/Scilly Isles

APCH

	N27	5
--	-----	---

	N32	5
--	-----	---

EGJA

St Annes/Alderney

APCH

	N08	5
--	-----	---

	N26	5
--	-----	---

EGNH

Blackpool

APCH

	N10	3
--	-----	---

*See Reason Code table on page R1

	Type	Procedure	Reason*
EGNV			Teesside International
	APCH		
		N23	3
EGPO			Stornoway
	APCH		
		L36	3
		N18	3
		N36	3
EGTE			Exeter
	APCH		
		N26	3
EGYD			Cranwell
	SID		
		MID1B	5
EHEH			Eindhoven
	SID		
		EH5	22
ENBL			Forde/Bringeland
	APCH		
		J07	1
		J25	1
ENBN			Bronnoysund/Bronnoy
	APCH		
		J03	1
ENBS			Batsfjord
	APCH		
		J03	1
		J21	1
ENBV			Berlevag
	APCH		
		J06	1
		J24	1
ENHF			Hammerfest
	APCH		
		J04	1
		J22	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
ENHK			Hasvik
		APCH	
		J11	1
		J29	1
ENLK			Leknes
		APCH	
		J20	1
ENMH			Mehamn
		APCH	
		J17	1
		J35	1
ENNM			Namsos
		APCH	
		J07	1
		J25	1
ENRM			Rorvik/Ryum
		APCH	
		J04	1
		J22	1
ENRS			Rost
		APCH	
		J02	1
		J20	1
ENSH			Svolvaer/Helle
		APCH	
		J01	1
ENSS			Vardo/Svartnes
		APCH	
		J15	1
		J33	1
ENST			Stokka/Sandnessjoen
		APCH	
		J02	1
		J20	1
ENVV			Vadso
		APCH	
		J07	1
		J25	1

*See Reason Code table on page R1

	Type	Procedure	Reason*
EPPR			Pruszcz Gdanski
		APCH	
		N27-X	5
		N27-Y	5
		N27-Z	5
ETNG			Geilenkirchen
		SID	
		NG227	22
EVLA			Liepaja
		APCH	
		I24-Z	5
		V06-Z	5
		V24-Z	5
		SID	
		LEP1E	5
		LEP1G	5
HLLM			Tripoli/Mitiga Intl
		APCH	
		D10	2
		D28	2
KDLH			Duluth Intl
		APCH	
		T09	19
KDYS			Abilene/Dyess AFB
		APCH	
		T16-W	19
		T34-W	19
KEGI			Crestview/Duke Fld, Eglin AF A
		APCH	
		T18	19
		T36	19
KENV			Wendover
		APCH	
		R08	5
KHTO			East Hampton
		APCH	
		R10-X	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
KLSV			Las Vegas/Nellis AFB
		APCH	
		T21LX	19
KMTC			Mount Clemens/Selfridge ANGB
		APCH	
		T01	19
		T19	19
KMTN			Baltimore/Martin State
		APCH	
		T15	19
		V15	11
KNDZ			Milton/Whiting Fld NAS South
		APCH	
		T32	19
KPAM			Panama City/Tyndall AFB
		APCH	
		T14LZ	19
		T32RZ	19
KVKX			Friendly/Potomac Airfield
		APCH	
		R06	5
KVPS			Valparaiso/Destin-Ft Walton Be
		APCH	
		T01	19
		T12	19
		T19	19
		T30	19
LFBD			Bordeaux/Merignac
		SID	
		ROYA5Z	5
		SAU5Z	5
		VAVI5Z	5
LHKE			Kecskemet
		APCH	
		N12	5
		N30	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
LHNY			Nyiregyhaza
		APCH	
		H18-Z	5
		H36-Z	5
LHPA			Papa AB
		APCH	
		N16	5
LIMS			Piacenza
		SID	
		GEN6Q	22
		KALM6Q	22
MHTG			Tegucigalpa/Toncontin Intl
		APCH	
		H20	13
MRLB			Liberia/Daniel Oduber Quiros I
		APCH	
		V07	2
MSSS			San Salvador/Ilopango Intl
		APCH	
		V15	5
N07			Lincoln Park
		APCH	
		R01	5
		R19	5
N40			Pittstown/Sky Manor
		APCH	
		R07	5
		R25	5
		V07	5
N85			Pittstown/Alexandria
		APCH	
		D08	5
NTAA			Tahiti/Faa'a
		SID	
		ARIT4E	5
		ARIT4W	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
NTTE			Tetiaroa
		SID	
		TAVI1E	5
		TAVI1W	5
NTTG			Rangiroa
		APCH	
		V27-X	5
NZTK			Takaka
		APCH	
		R18-Y	5
NZWB			Woodbourne
		STAR	
		NORTHV	27
		WESTV	27
OEGT			Guriat Domestic
		APCH	
		V28	2
OPLA			Lahore/Allama Iqbal Intl
		APCH	
		V18LZ	3
		V18RZ	3
		V36L	3
		V36R	3
OPRK			Rahim Yar Khan/Sheikh Zayed In
		APCH	
		V01	3
PACJ			Crooked Creek
		APCH	
		R14	5
		SID	
		AJOFY1	5
PARS			Russian Mission
		APCH	
		R36	5
RJFN			Nyutabaru AB
		APCH	
		T28-1	19
		T28-2	19

*See Reason Code table on page R1

	Type	Procedure	Reason*
RKSM			Seoul Domestic
		APCH	
		I20-Z	22
		L19-Z	22
		L20-Z	22
SKUL			Tulua/Heriberto Gil Martinez
		APCH	
		V02	5
UHHM			Chegdomyn
		APCH	
		H13	5
		H31	5
UHPK			Ust-Kamchatsk
		STAR	
		DOMUD2	5
UIUU			Ulan-Ude/Mukhino
		APCH	
		I08-Y	5
		N08-Y	5
		N08-Z	5
		STAR	
		BULE5H	5
		OSTU5H	5
		RIDL5H	5
	TOLG5H	5	
UKHK			Kremenchuk/Velyka Kokhnyvka
		APCH	
		N36	5
URML			Makhachkala/Uytash
		SID	
		H1A	5
		TA1A	5
		STAR	
		BUIK1E	5
		BUIK1G	5
		GUDE1E	5
	GUDE1G	5	

*See Reason Code table on page R1

	Type	Procedure	Reason*
URRT			Taganrog/Yuzhny
		APCH	
		N10-X	5
		N28-X	5
UWKD			Kazan
		APCH	
		V11-X	5
USWK			Krasny Kut
		SID	
		X003	5
		X070	5
		X107	5
		X130	5
		X156	5
	X351	5	
VTBK			Nakhon Pathom/Kamphaeng Saen
		APCH	
		V21	2
WAJI			Sarmi/Mararena
		APCH	
		H13	5
		H31	5
WAKE			Mappi/Bade
		APCH	
		H02	5
		H20	5
WASA			Maybrat/Ayawasi
		APCH	
		H09	5
		H27	5
WASI			Inanwatan
		APCH	
		H08	5
		H26	5
WAUM			Merdey
		APCH	
		H27	5

*See Reason Code table on page R1

	Type	Procedure	Reason*
WAYK			Kokonao
		APCH	
		H13	5
ZYTX			Shenyang/Taoxian
		STAR	
		ANS02A	22
		ANS2AV	22
		TOS02A	22
		TOS2AV	22

*See Reason Code table on page R1

Reason Table HWL

Code	Explanation
1	procedure based on SCAT GBAS system, not accepted by Data Packer
2	VOR and VOR/DME APP published without multiple indicator, VOR-only APP excluded
3	two approaches of same type: only one requires DME. Non-DME-based approach excl.
5	procedure authorized for CAT A aircraft only
11	procedure contains AF (Arc-to-Fix) Path Termination, based on invalid Navaid
13	RNAV (RNP) and RNAV (GNSS) APP published without multiple indicator, RNP APP excluded
19	procedure requires military TACAN receiver
22	procedure contains CR (Course-to-Radial) Path Termination, based on invalid type of Navaid
27	STAR that does not have a common start fix

If you have any questions concerning this report, please contact your FMS Customer Support at fms.support@lhsystems.com or call +41 44 828 65 55