

Procedures removed from ARINC output Cycle 2205

Type	Procedure	Transition	Reason
CPZ3			Trenton / Mountain View, ON
	APCH		
	R06R	LEPAP	source inconsistency, not published in CAP/RCAP
	R06R	SEGEP	source inconsistency, not published in CAP/RCAP
	R06R	ZASER	source inconsistency, not published in CAP/RCAP
	R06R		source inconsistency, not published in CAP/RCAP
	R24L	ALIRA	source inconsistency, not published in CAP/RCAP
	R24L	GADEN	source inconsistency, not published in CAP/RCAP
	R24L	ODBAK	source inconsistency, not published in CAP/RCAP
	R24L		source inconsistency, not published in CAP/RCAP
EGVN			Brize Norton AB
	SID		
	ALPHA	RW07	Different Endfixes not possible
	ALPHA	RW25	Different Endfixes not possible
	BRAVO	RW07	Different Endfixes not possible
	BRAVO	RW25	Different Endfixes not possible
FMMS			Sainte Marie
	APCH		
	N01	SM	Notam A1096/19
	N01		Notam A1096/19
	N19	SM	Notam A1096/19
	N19		Notam A1096/19

Type	Procedure	Transition	Reason
FZMA			Bukavu / Kavumu
	APCH		
	R35	DOPEM	Incorrect Source: AIRAC AIP SUP S3006/06
	R35	OSLON	Incorrect Source: AIRAC AIP SUP S3006/06
	R35		Incorrect Source: AIRAC AIP SUP S3006/06
HKLK			Lokichoggio
	APCH		
	H27	EPSUT	HK Notam B0002/21
	H27		HK Notam B0002/21
HLLT			Tripoli Intl
	SID		
	GARU1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	MIS1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	SARK1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1C	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1G	RW27	VOR/DME TPI new coordinates, procedures not updated
	WLD1C	RW09	VOR/DME TPI new coordinates, procedures not updated

Type	Procedure	Transition	Reason
STAR	GRT1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	GRT1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	IZD1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	IZD1E	RW27	VOR/DME TPI new coordinates, procedures not updated
	MIS1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1A	RW09	VOR/DME TPI new coordinates, procedures not updated
	SINA1E	RW27	VOR/DME TPI new coordinates, procedures not updated

KCLR

Calipatria / Cliff Hatfield Mem, CA

APCH

R08	BOREN
-----	-------

R08

Type	Procedure	Transition	Reason
KEUG			
Eugene / Mahlon Sweet Fld, OR			
APCH			
R34LZ	DRAIN		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34LZ	SHEDD		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34LZ	VAUGN		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34LZ	VIDAS		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34LZ			FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34RZ	SAGIN		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34RZ	SHEDD		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34RZ	VAUGN		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34RZ	VIDAS		FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.
R34RZ			FAF ICAVA and ZIMKE moved with NFDD 156/2018 for R34LY and R34RY, but not for R34LZ and R34RZ.

KLCK			
Columbus / Rickenbacker Intl, OH			
APCH			
R05L	GAILL		
R05L	HIGID		
R05L	TARTO		
R05L			not trusted due to calc. angle of 3.16°

Type	Procedure	Transition	Reason
LSMD			Dubendorf
APCH			
	H29-X	MD519	coding table not up to date
	H29-X		coding table not up to date
	H29-Y	MD514	coding table not up to date
	H29-Y	MD516	coding table not up to date
	H29-Y		coding table not up to date
SBGW			Guaratingueta, SP
APCH			
	N02-A	GGT	procedure not compatibel with FMS requirements
	N02-A		procedure not compatibel with FMS requirements
	N20-B	GGT	procedure not compatibel with FMS requirements
	N20-B		procedure not compatibel with FMS requirements
SBPA			Porto Alegre / Salgado Filho Intl, RS
APCH			
	V29-Y	AJAX	AIRAC SB MAP 05/22
	V29-Y	GIMPU	AIRAC SB MAP 05/22
	V29-Y		AIRAC SB MAP 05/22
UEEE			Yakutsk
APCH			
	J05R	EE001	NOTAM UE A5084/21 (-30APR22EST), RWY 05R displaced by 150m towards ARP, RWY 05R avbl for TKOF only
	J05R	EE002	NOTAM UE A5084/21 (-30APR22EST), RWY 05R displaced by 150m towards ARP, RWY 05R avbl for TKOF only
	J05R	EE003	NOTAM UE A5084/21 (-30APR22EST), RWY 05R displaced by 150m towards ARP, RWY 05R avbl for TKOF only

Type	Procedure	Transition	Reason
UHMD	Provideniya Bay		
	SID		
	BAMRI	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	BAMRI	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIMRA	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIMRA	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LALOK	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LALOK	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
MONUD	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.	
MONUD	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.	

Type	Procedure	Transition	Reason
STAR			
	ABINA	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	ABINA	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	GIRLO	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	INGUS	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	INGUS	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LIKOK	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	LIKOK	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	MONUD	RW01	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.
	MONUD	RW19	not possible to verify RWY position with GE (ice/snow). Different RWY brgds calc/published.

Type	Procedure	Transition	Reason
UHMP			Pevek
	APCH		
	I35-X	PWK	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	I35-X		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	I35-Y	BM	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	I35-Y		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	I35-Z	MP009	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	I35-Z	MP020	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	I35-Z		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	J17	MP003	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	J17	MP004	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	J17		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	J35	MP009	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	J35	MP020	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	J35		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	L35-X	PWK	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	L35-X		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	N35-X	B	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	N35-X		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	N35-Y	BM	NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.
	N35-Y		NTM C6132/21 (-31MAY22), RWY 35 landing THR displaced by 1250 m.

Type	Procedure	Transition	Reason
YPTN			Tindal, NT
	APCH		
	I14-Z	TN	SUP H 27/22
	I14-Z		SUP H 27/22
ZBDH			Qinhuangdao / Beidaihe
	SID		
	OTB01D	RW08	SUP 48/19 expired
	OTB11D	RW26	SUP 48/19 expired
	OTB12D	RW26	SUP 48/19 expired
	P5101D	RW08	SUP 48/19 expired
	P5111D	RW26	SUP 48/19 expired
	P5112D	RW26	SUP 48/19 expired
	STAR		
	OTB01A	RW08	SUP 48/19 expired
	OTB11A	RW26	SUP 48/19 expired
	P5101A	RW08	SUP 48/19 expired
	P5111A	RW26	SUP 48/19 expired

Type	Procedure	Transition	Reason
APCH			
	I26	QHD	SUP 48/19 expired
	I26		SUP 48/19 expired
	L26	QHD	SUP 48/19 expired
	L26		SUP 48/19 expired
	V08	R242	SUP 48/19 expired
	V08	R251	SUP 48/19 expired
	V08	R269	SUP 48/19 expired
	V08	R278	SUP 48/19 expired
	V08		SUP 48/19 expired
	V26	QHD	SUP 48/19 expired
	V26		SUP 48/19 expired

ZBDT

Datong / Yungang

SID			
LAR01D	RW14		SUP 20/19 expired
LAR11D	RW32		SUP 20/19 expired
SEL01D	RW14		SUP 20/19 expired
SEL11D	RW32		SUP 20/19 expired
TOD01D	RW14		SUP 20/19 expired
TOD11D	RW32		SUP 20/19 expired

Type	Procedure	Transition	Reason
STAR			
	LAR01A	RW14	SUP 20/19 expired
	LAR11A	RW32	SUP 20/19 expired
	LAR12A	RW32	SUP 20/19 expired
	SEL01A	RW14	SUP 20/19 expired
	SEL02A	RW14	SUP 20/19 expired
	SEL11A	RW32	SUP 20/19 expired
	TOD01A	RW14	SUP 20/19 expired
	TOD02A	RW14	SUP 20/19 expired
	TOD11A	RW32	SUP 20/19 expired

Type	Procedure	Transition	Reason
APCH			
I32		BJZ13	SUP 20/19 expired
I32		BJZNO	SUP 20/19 expired
I32		BJZSO	SUP 20/19 expired
I32			SUP 20/19 expired
L32		BJZ13	SUP 20/19 expired
L32		BJZNO	SUP 20/19 expired
L32		BJZSO	SUP 20/19 expired
L32			SUP 20/19 expired
N14		J	SUP 20/19 expired
N14			SUP 20/19 expired
V14		BJZ	SUP 20/19 expired
V14		BJZ14	SUP 20/19 expired
V14		BJZ16	SUP 20/19 expired
V14			SUP 20/19 expired
V32		BJZ13	SUP 20/19 expired
V32		BJZNO	SUP 20/19 expired
V32		BJZSO	SUP 20/19 expired
V32			SUP 20/19 expired

Type	Procedure	Transition	Reason
ZGCD			Changde / Taohuayuan
	SID		
	LIN01D	RW02	SUP 43/19 expired
	LIN11D	RW20	SUP 43/19 expired
	LLC01D	RW02	SUP 43/19 expired
	LLC03D	RW02	SUP 43/19 expired
	LLC11D	RW20	SUP 43/19 expired
	LLC13D	RW20	SUP 43/19 expired
	NOM01D	RW02	SUP 43/19 expired
	NOM11D	RW20	SUP 43/19 expired
	STAR		
	LIN01A	RW02	SUP 43/19 expired
	LIN11A	RW20	SUP 43/19 expired
	LLC01A	RW02	SUP 43/19 expired
	LLC02A	RW02	SUP 43/19 expired
	LLC03A	RW02	SUP 43/19 expired
	LLC11A	RW20	SUP 43/19 expired
	LLC13A	RW20	SUP 43/19 expired
	NOM01A	RW02	SUP 43/19 expired
	NOM02A	RW02	SUP 43/19 expired
	NOM11A	RW20	SUP 43/19 expired

Type	Procedure	Transition	Reason
APCH			
I02		14ICD	SUP 43/19 expired
I02		CD	SUP 43/19 expired
I02		ICD14	SUP 43/19 expired
I02			SUP 43/19 expired
L02		14ICD	SUP 43/19 expired
L02		CD	SUP 43/19 expired
L02		ICD14	SUP 43/19 expired
L02			SUP 43/19 expired
N02		14ICD	SUP 43/19 expired
N02		CD	SUP 43/19 expired
N02		ICD14	SUP 43/19 expired
N02			SUP 43/19 expired
N20		F	SUP 43/19 expired
N20		ICD11	SUP 43/19 expired
N20		LIN	SUP 43/19 expired
N20			SUP 43/19 expired

ZGZH

Liuzhou / Bailian

SID			
LBN03D		RW34	SUP 37/18 expired
LBN13D		RW16	SUP 37/18 expired

Type	Procedure	Transition	Reason
STAR			
	LBN03A	RW34	SUP 37/18 expired
	LBN04A	RW34	SUP 37/18 expired
	LBN05A	RW34	SUP 37/18 expired
	LBN14A	RW16	SUP 37/18 expired
	LBN15A	RW16	SUP 37/18 expired

Type	Procedure	Transition	Reason
APCH			
I34		DR	SUP 37/18 expired
I34		LIU	SUP 37/18 expired
I34		LIU12	SUP 37/18 expired
I34			SUP 37/18 expired
L34		DR	SUP 37/18 expired
L34		LIU	SUP 37/18 expired
L34		LIU12	SUP 37/18 expired
L34			SUP 37/18 expired
N16		JV	SUP 37/18 expired
N16			SUP 37/18 expired
N34		DR	SUP 37/18 expired
N34		LIU12	SUP 37/18 expired
N34			SUP 37/18 expired
V16		LIU	SUP 37/18 expired
V16			SUP 37/18 expired
V34		LIU	SUP 37/18 expired
V34		LIU12	SUP 37/18 expired
V34			SUP 37/18 expired

Type	Procedure	Transition	Reason
ZHES			Enshi / Xu Jiaping
	SID		
	DYG01D	RW19	SUP 49/19 expired
	DYG11D	RW01	SUP 49/19 expired
	FLG01D	RW19	SUP 49/19 expired
	FLG11D	RW01	SUP 49/19 expired
	YIH01D	RW19	SUP 49/19 expired
	YIH11D	RW01	SUP 49/19 expired
	ZHJ01D	RW19	SUP 49/19 expired
	ZHJ11D	RW01	SUP 49/19 expired

Type	Procedure	Transition	Reason
STAR	DYG01A	RW01	SUP 49/19 expired
	DYG02A	RW01	SUP 49/19 expired
	DYG11A	RW19	SUP 49/19 expired
	FLG01A	RW01	SUP 49/19 expired
	FLG11A	RW19	SUP 49/19 expired
	YIH01A	RW01	SUP 49/19 expired
	YIH11A	RW19	SUP 49/19 expired
	YIH12A	RW19	SUP 49/19 expired
	ZHJ01A	RW01	SUP 49/19 expired
	ZHJ02A	RW01	SUP 49/19 expired
	ZHJ11A	RW19	SUP 49/19 expired

Type	Procedure	Transition	Reason
APCH			
I01		ENH	SUP 49/19 expired
I01		ENH10	SUP 49/19 expired
I01		ENH13	SUP 49/19 expired
I01			SUP 49/19 expired
L01		ENH	SUP 49/19 expired
L01		ENH10	SUP 49/19 expired
L01		ENH13	SUP 49/19 expired
L01			SUP 49/19 expired
V01		ENH	SUP 49/19 expired
V01		ENH10	SUP 49/19 expired
V01		ENH13	SUP 49/19 expired
V01			SUP 49/19 expired
V19		ENH	SUP 49/19 expired
V19			SUP 49/19 expired

Type	Procedure	Transition	Reason
ZLYL			Yulin / Yuyang
	SID		
	APO01D	RW16	SUP 39/19 expired
	APO11D	RW34	SUP 39/19 expired
	MUD01D	RW16	SUP 39/19 expired
	MUD11D	RW34	SUP 39/19 expired
	NNW01D	RW16	SUP 39/19 expired
	NNW11D	RW34	SUP 39/19 expired
	VED01D	RW16	SUP 39/19 expired
	VED11D	RW34	SUP 39/19 expired
	STAR		
	APO01A	RW16	SUP 39/19 expired
	APO11A	RW34	SUP 39/19 expired
	MUD01A	RW16	SUP 39/19 expired
	MUD11A	RW34	SUP 39/19 expired
	NNW01A	RW16	SUP 39/19 expired
	NNW11A	RW34	SUP 39/19 expired
	VED01A	RW16	SUP 39/19 expired
	VED11A	RW34	SUP 39/19 expired

Type	Procedure	Transition	Reason
APCH			
I16		R340N	SUP 39/19 expired
I16		YLX	SUP 39/19 expired
I16			SUP 39/19 expired
I34		R122P	SUP 39/19 expired
I34		R186T	SUP 39/19 expired
I34		YLX	SUP 39/19 expired
I34			SUP 39/19 expired
L16		R340N	SUP 39/19 expired
L16		YLX	SUP 39/19 expired
L16			SUP 39/19 expired
L34		R122P	SUP 39/19 expired
L34		R186T	SUP 39/19 expired
L34		YLX	SUP 39/19 expired
L34			SUP 39/19 expired
V16		R340N	SUP 39/19 expired
V16		YLX	SUP 39/19 expired
V16			SUP 39/19 expired
V34		R122P	SUP 39/19 expired
V34		R186T	SUP 39/19 expired

Type	Procedure	Transition	Reason
	V34	YLX	SUP 39/19 expired
	V34		SUP 39/19 expired

ZSLY

Linyi / Qiyang

SID			
	P5811D	RW01	SUP 12/20 expired
	P5812D	RW19	SUP 12/20 expired
	P6011D	RW01	SUP 12/20 expired
	P6012D	RW19	SUP 12/20 expired
STAR			
	P581A	RW01	SUP 12/20 expired
	P582A	RW19	SUP 12/20 expired
	P583A	RW01	SUP 12/20 expired
	P601A	RW01	SUP 12/20 expired
	P602A	RW19	SUP 12/20 expired
	P603A	RW01	SUP 12/20 expired
	P604A	RW19	SUP 12/20 expired

Type	Procedure	Transition	Reason
APCH			
	I01-Y	LNy	SUP 12/20 expired
	I01-Y	R242K	SUP 12/20 expired
	I01-Y		SUP 12/20 expired
	I19-Y	LNy	SUP 12/20 expired
	I19-Y	R315K	SUP 12/20 expired
	I19-Y		SUP 12/20 expired
	L01-Y	LNy	SUP 12/20 expired
	L01-Y	R242K	SUP 12/20 expired
	L01-Y		SUP 12/20 expired
	L19-Y	LNy	SUP 12/20 expired
	L19-Y	R315K	SUP 12/20 expired
	L19-Y		SUP 12/20 expired
	V01	LNy	SUP 12/20 expired
	V01	R242K	SUP 12/20 expired
	V01		SUP 12/20 expired
	V19	LNy	SUP 12/20 expired
	V19	R314K	SUP 12/20 expired
	V19		SUP 12/20 expired