
Flight Safety Alert

AIRAC 1808 – Issue 5

AIP AD2 ENTC 5-5 effective 26th May 2016

ENTC Tromso Langnes

APCH ILS 19 and LOC 19

- ALT constraint at waypoint TC501 should read **+5000ft** instead of +4500ft.

Navdata will be updated effective AIRAC cycle 1809.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
25th July 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com