
Flight Safety Alert

AIRAC 1905 – Issue 2

AIRAC SUP 01/2019 effective 03rd January 2019

LT Turkey

Waypoint DRAMO

- DRAMO coordinates should read **N41-02-04.00 E026-36-40.00** (N41-02.1 E026-36.7)
instead of N40-54-15.00 E026-36-11.00 (N40-54.3 E026-36.2)

(used in **LTBA / LTFJ / LTFM** STARs)

Navdata will be updated effective AIRAC cycle 1906.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
17th April 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com