

---

## Flight Safety Alert

### **AIRAC 2010 – Issue 1**

**AIP SK effective 16th July 2020**

### **SKMR Monteria Los Garzones**

---

#### **APCH VOR RWY 32, MTR transition**

- **Outbound track should read 136deg** instead of 130deg.

Navdata will be updated effective AIRAC cycle 2011.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Thursday, 10<sup>th</sup> September 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)