
Navigation Database Addendum

AIRAC 1805 – Issue 3

SUP FZ AIRAC 01/18 effective 26th April 2018

FZQA Lubumbashi Luano

All APCHs for RWY 07

Late receipt of document. The following procedures have been completely revised, they should not be used:

- **RNAV 07** and **VOR 07**.

The following procedures are missing:

- **VOR Z 07, VOR Y 07, ILS/LOC Z 07, ILS/LOC Y 07, ILS/LOC X 07.**

Navdata will be updated effective AIRAC cycle 1806.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
25th April 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>

For any inquiries, please contact fms.support@lhsystems.com