

## Navigation Database Addendum

### **AIRAC 1806 – Issue 1**

**NOTAM A1386/18 effective 11th April 2018**

### **OIIE Tehran Imam Khomains Intl**

---

#### **APCH VOR 11L, Runway 11L**

Until 11th June 2018 (est.)

- RWY 11L threshold should read **TEMPO displaced by 610 meters** instead of no threshold displacement.
- **VOR 11L apch is not aligned** to the TEMPO displaced RWY 11L threshold.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
27<sup>th</sup> April 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)