

## Navigation Database Addendum

### **AIRAC 1811 – Issue 2**

### **VIDP Indira Gandhi Intl**

---

#### **APCH I09, I10**

Missed approach instructions for the I09 and I10 should read:

"Climb straight ahead to 2600ft. **At 10D DPN turn right** heading 130°M..." instead of "Climb straight ahead to 2600ft. Climbing right turn to heading 130°M..."

Navdata will be updated effective AIRAC cycle 1812.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
1<sup>st</sup> October 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)