

Navigation Database Addendum

AIRAC 1812 – Issue 6

SUP 012/2018 & SUP 013/2018

LDDU Dubrovnik Cilipi

Runway 12/30 work in progress

Phase 2: (estimated from end of November until mid December – activated by Notam)

- runway shortened (NOT amended in database)
- additional procedures for RWY12 included in database:

- L z RWY12
- VOR z RWY12
- LOC z RWY 12

following procedures are suspended during phase 2:

- L RWY12
- VOR RWY12
- ILS or LOC RWY12
- RNAV (GNSS) RWY12

Navdata will be updated effective AIRAC cycle 1813.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
5th November 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com