
Navigation Database Addendum

AIRAC 1813 – Issue 10

AMDT SP 25/18 effective 6th December 2018; NOTAM SP A4880/18 effective 20th November 2018

SPIM Lima FIR

AWY UT311, UP776

Due to postponement of AMDT 25/18

- airway UT311 is missing in database.
- airway UP776 should not be used.

Navdata will be updated effective AIRAC cycle 1901.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
4th December 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com