
Navigation Database Addendum

AIRAC 1813 – Issue 4

USTP EC-1 effective 8th November 2018

KDTW Detroit Metropolitan Wayne County

ILS Y RWY 22R - misap holding

Misap holding at DOHNT should read inbound 117 deg right turn instead of 297 deg right turn.

Navdata will be updated effective AIRAC cycle 1901.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
21st November 2018

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com