

Navigation Database Addendum

AIRAC 1902 – Issue 8

NOTAM B0356/19 effective 16th January 2019

LEBZ Badajoz Talavera La Real

- **APCH ILS Z RWY 31**
- **APCH LOC Z RWY 31**

ILS Z RWY 31 and LOC Z RWY 31 are not included in FMS database.

Navdata will be updated effective AIRAC cycle 1903.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
17th January 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com