

---

## Navigation Database Addendum

### **AIRAC 1902 – Issue 3**

#### **SUP 12/2018 LDDU reconstruction of pavement on RWY 12/30**

### **LDDU Dubrovnik Cilipi**

---

#### **Runway 12**

Phase III: (estimated from mid December until March 2019 – activated by Notam)

- Runway 12/30 shortened from 3299 meters to 2099 meters (reflected as such in database)
- Threshold RWY 12 temporarily displaced by 1050 meters towards threshold RWY 30
- Additional procedures published and added to database:

- L y RWY 12
- VOR y RWY 12
- LOC y RWY 12
- RNAV (GNSS) y RWY 12

Instrument Approach ILS RWY 12 temporarily suspended

Check supplement 012/2018 for details.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
15<sup>th</sup> January 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)