

Navigation Database Addendum

AIRAC 1903 – Issue 10

AIP ENR 3.4-5 effective 13th September 2018

GMFF Fes Saiss Intl

Waypoint UROLU

Waypoint UROLU **N33 32.7 W005 32.6 (N33-32-40.20 W005-32-35.81)** is missing in the database.

Navdata will be updated effective AIRAC cycle 1904.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
22nd February 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com