
Navigation Database Addendum

AIRAC 1903 – Issue 12

NOTAM O0111/19 effective 14th February 2019

SBCY Cuiaba Marechal Rondon Intl

APCH VOR/DME RWY 35

Late receipt of document, missed approach not updated:

Missed approach should read:

Climb to 4000ft on RDL 358 CIA to 15 DME CIA for holding.(Inbound 178deg / Right turn)

instead of:

Climb to 3000ft on RDL 350.

Navdata will be updated effective AIRAC cycle 1904.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
25th February 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

