
Navigation Database Addendum

AIRAC 1904 – Issue 10

NOTAM J0145 - J0160, J0161, K0235, Z0197, Z0198, Z200 effective 12th March 2019

SBBS Brasilia SB Brazil

Navaid RCL;AWY Z41

Late receipt of NOTAMs, following data not updated:

- NDB RCL should read GERTU, position unchanged
- Airway W30 should read Z41.

Navdata will be updated effective AIRAC cycle 1905.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
19th March 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com