

Navigation Database Addendum

AIRAC 1904 – Issue 13

AIRAC AMDT 06/17 effective 27th April 2017

CYYZ Toronto Lester B Pearson Intl CY Canada

APCH LOC 23

MISAP Holding at "IKDOT" should read "right hand pattern" instead of "left hand pattern"

Navdata will be updated effective AIRAC cycle 1905.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
20th March 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com