

Navigation Database Addendum

AIRAC 1904 – Issue 3

SUP 07/19 effective 28th February 2019

LEZL Sevilla San Pablo

Runway 09/27

Runway 09/27 resurfacing works will be carried out in 5 phases from 28 FEB 19 until 30 APR 20 EST.

Runway 27 “PHASE 1”

During “PHASE 1” announced by NOTAM, a temporary 1063m displaced THR 27 will be set. The Database during this phase **does not** reflect the correct coordinates.

The new THR 27 coordinates should read N37 25 04.67 / W005 53 10.00 elevation 95ft instead of N37 25 04.81 / W005 52 26.77 elevation 111ft.

	TORA (m)	TODA(m)	ASDA(m)	LDA(m)
RW09	2299	2359	2299	2299 (2144 code D and E)
RW27	2299	2360	2299	2299

RWY 27 ILS/DME ISV, GP and LOC will be out of service.

Runway 09 "PHASE 2"

During "PHASE 2" announced by NOTAM, a temporary 510m displaced THR 09 will be set. The Database during this phase **does not** reflect the correct coordinates.

The new THR 09 coordinates should read N37 25 04.42 / W005 54 22.77 elevation 86ft instead of N37 25 04.35 / W005 54 43.50 elevation 83ft.

	TORA (m)	TODA(m)	ASDA(m)	LDA(m)
RW09	2852	2910	2852	2852
RW27	2852	2912	2852	2852 (2560 code D and E)

RWY 09 ILS/DME ISE, GP and LOC will be out of service.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
12th February 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com