
Navigation Database Addendum

AIRAC 1905 – Issue 13

SUP A17/19 effective 25th April 2019

SLCB Cochabamba Jorge Wilsterman International

APCH VOR U, V, RNAV Z RWY 32

Late receipt of document, following approaches missing:

VOR U, V RWY 32

RNAV Z RWY 32

Navdata will be updated effective AIRAC cycle 1906.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
24th April 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com