

---

## Navigation Database Addendum

### **AIRAC 1905 – Issue 16**

**SUP A21/18 effective 31st January 2019**

### **MPZL Panama FIR, SKED Colombia FIR**

---

#### **AWY UM542**

Airway UM542 within Panama and Colombia FIR should read ...TBG - RODAX - DABON - TINPA - UMGOS... instead of ...TBG - UMGOS... Total distance and tracks are unchanged.

Navdata will be updated effective AIRAC cycle 1906.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
29<sup>th</sup> April 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)