

---

## Navigation Database Addendum

### **AIRAC 1906 – Issue 4**

**SUP A18/19 effective 23rd May 2019**

### **SLLP La Paz El Alto Intl.**

---

#### **APCH ILS/LOC Y, Z, V , VOR Z RWY 10**

Late receipt of document, following approaches missing:

ILS / LOC Y, Z, V RWY 10

VOR Z RWY 10

Navdata will be updated effective AIRAC cycle 1907.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
8<sup>th</sup> May 2019

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)