

---

## Navigation Database Addendum

### **AIRAC 2010 – Issue 11**

**SUP EY 03/20 effective 1st May 2020**

### **EYSA Siauliai Intl**

---

#### **Runway 32R**

- From 01 MAY until 30 SEP 20 temporary displacement of landing threshold by 455m is not reflected in database.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Thursday, 10<sup>th</sup> September 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)