

---

## Navigation Database Addendum

### **AIRAC 2010 – Issue 8**

**AIRAC AMDT EP 231/20 effective 10th September 2020**

### **EPLB Lublin**

---

#### **APCH RNP 07**

VPA between IF “LB394” and FAF “LB398” should read **3.3deg** instead of 3.5deg.

Navdata will be updated effective AIRAC cycle 2011.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 9<sup>th</sup> September 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)