
Navigation Database Addendum

AIRAC 2011 – Issue 12

NOTAM EPCE B3502/20 effective 28th July 2020

EPCE Cewice

All APCH for RWY 07, Runway 07

- **Until 2010272200EST, RWY 07 landing threshold should read displaced towards RWY 25 by 1418m instead of nil displacement.**
- **Until 2010272200EST, APCHs RWY 07 are not aligned to the displaced landing threshold.**

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 7th October 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com