

## Navigation Database Addendum

### **AIRAC 2011 – Issue 2**

**NOTAM A3575/20 effective 18th September 2020**

### **MUCU Santiago de Cuba Antonio Maceo Intl**

---

#### **Runway 10**

Runway 10 threshold displacement of 1000m **not** included in database.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Wednesday, 16<sup>th</sup> September 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)