
Navigation Database Addendum

AIRAC 2012 – Issue 14

NFDD 191/2020 and Transmittal Letter 20-23 effective 5th November 2020

KORD Chicago O'Hare Intl

Holding OBK VOR/DME; APCH RNAV (GPS) RWY 09L and RNAV (GPS) RWY 27R

Missed APCH HLDG at VOR/DME OBK should read Inbound 092deg, RIGHT Turn, **9NM** instead of Inbound 092deg, RIGHT Turn, 7NM.

Navdata will be updated effective AIRAC cycle 2013.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 4th November 2020

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com