

---

## Navigation Database Addendum

### **AIRAC 2107 – Issue 11**

**NOTAM EP F3806/21 effective 30<sup>th</sup> June 2021**

### **EPLY Leczyca**

---

#### **APCH RWY 10**

#### **Runway 10**

RWY 10 landing threshold displacement of 480m is **not included** in database.

Coded APCHs do not lead to threshold.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Friday, 9<sup>th</sup> July 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)