

---

## Navigation Database Addendum

### **AIRAC 2107 – Issue 14**

**AIRAC AMDT SB MAP 07/21 effective 15th July 2021**

### **SBKP Campinas Viracopos Intl**

---

#### **APCH RNP X 33**

#### **Waypoint KP172**

Step down fix **KP172** S23-02.5 W047-05.2 (S23-02-31.00 W047-05-10.55) between ARNIV and RWY 33 **missing**.  
ALT constraint should read "at or above 2800ft".

Navdata will be updated effective AIRAC cycle 2108.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Tuesday, 13<sup>th</sup> July 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)