

Navigation Database Addendum

AIRAC 2108 – Issue 2

SUP 08/21 effective 26th May 2021

EYSA Siauliai Intl

APCHs RWY 32R

Runway 32R

RWY 32R threshold **displacement** of 455m is **not included** in database.

Vertical Guidance should not be used.

Coded APCHs do not lead to threshold.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 14th July 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com